RECEIVED

Form 3160- 5

UNITED STATES

JUL 23 2009 |

FORM APPROVED

(August, 2007)	DEPARTMENT OF			•	1004- 0137	
	BUREAU OF LAND) MANAGEMÊN <u>T</u>	au of Land Manage	ment Expires Ju	ily 31, 2010	
Ç1	INDRY NOTICES AND		armington Field Off	P	<i>A</i> -1400	
	NMNM-1409 6 If Indian, Allottee, or Tribe Name					
	not use this form for propo doned well. Use Form 3160			i manin, monec, or me	re realite	
SUBMIT IN	TRIPLICATE - Other Ins	tructions on page 2.	,	7 If Unit or CA Agreement	Name and/or No	
Type of Well						
X Oil Well Gas Well		8 Well Name and No				
Name of Operator	,			SMITH	#4	
UESTAR EXPLORATION AN	D PRODUCTION COMPA			9 API Well No		
3a Address 050 17TH STREET, SUITE 500)	3b Phone No (incl	ude area code)	30-045-21645		
DENVER, CO 80265	,	(303)	672-6900	10 Field and Pool, or Exploratory Area		
Location of Well (Footage, Sec., T., R	, M, or Survey Description)	Lat.		ESCRITO GALLUP		
\$E NW 1900'	1710' 13 T 24N R	911/ Lana		11 County or Parish, State		
FNL	FWL 13 T 24N R	8W Long.		SAN JUAN	NEW MEXICO	
12. CHECK APPROPE	RIATE BOX(S) TO INDICA	TE NATURE OF NO	TICE, REPORT, OF	ROTHER DATA		
TYPE OF SUBMISSION		7	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Sta	art/ Resume) \ \ \Pi \w	ater Shut-off	
		·l				
	Altering Casing	Fracture Treat	Reclamation	w	ell Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Ot	her	
	Change Plans	Plug and abandon	Temporarily Ab	andon		
Final Abandonment Notice Convert to Injection		Plug back	back Water Disposal			
Questar Exploration and P order to condition the well	roduction Company raise	_	· -	y.		
		KCVL	JUL 24'09			
Questar returned the Smith	.0.10.1		CONS. DIV. DIST. 3			
If you have any questions of	or require additional infor	mation, please conta	act Sarah Boxley at	: (303) 672-6916.	<i>)</i> 131. 3	
14 I hereby certify that the foregoing is tru ame (Printed Typed)	ie and correct			,		
arah Boxley		Title		Permit Agent		
Signature Swahi	Boxley	Date	7/2	10/09	PTED FOR PACK	
	THIS SPACE FO	OR FEDERAL OR S	TATE OFFICE US	E	U.H. 9 & 2000	
					JUL 2 7 2505	
pproved by onditions of approval, if any are attach	ned Approval of this notice does	Title			NOTON FIELD COT	
rtify that the applicant holds legal or o	equitable title to those rights in the	ne subject lease Office		A A Property	ふく	
nich would entitle the app tle 18 U.S.C. Section 1001 AND Tit	licant to conduct operations de 43 U.S.C. Section 1212, make		on knowingly and willfu	lly to make any department	or agency of the Unite	
ates any false, fictitiousor fraudulent stater						
Instructions on page 2)		AIS	MOCD			

Questar E & P

Operations Summary Report

Legal Well Name: SMITH 4
Common Well Name: SMITH 4 Event Name:

WORKOVER

Start:

7/8/2009

Spud Date: End:

Contractor Name:

4 Corners Well Service

Rig Release:

Group:

Rig Name:

4 Corners Well Service

Rig Number: 6

Rig Name:	,	4 Cornei	rs Well S	Service		Rig Number: 6
Date	From - To	Hours	Code	Sub Code	Phase	Description of Operations
7/8/2009	06:00 - 16:00	10.00	LOC	3	,	On 7/8/2009 Road rig from Cortez to location. Tbg Size: 2-3/8" Csg.Size: 4-1/2" SITP:30, SICP: 20 Perfs: 5658' to 5864'.
7/9/2009	06:00 - 16:00	10.00	WCL	2		On 7/9/2009 RUSU. Blow down well. NDWH. Donut stuck in WH. Jar on donut for 2 hours, would not pull free. Soak w/marvel mystery oil. Jar for 20 min. Donut pulled free. NUBOP. Pick up on tbg. Attempt to remove donut. Bent top jt, pulled and laid down jt with donut. Pick up 3 jts of tbg, TIH and tbg fill 5947'. Lay down 3 jts and TOH visually inspecting and standing back 90 stds of tbg. Lay down bottom 2 jts. Pitted but found no holes. Cone bit, bit sub and SN on bottom. Tbg was landed at 5904.29' KB, 40' below bottom perf. Start in hole w/collar, 1 jt of tbg and SN. The first stand had tweaked jt on bottom from tongs. Lay down bottom jt on first stand. Inspected stds in derrick. Found 3 more tweaked joints in first row. TIH inspecting all stds for bent tbg Had to lay down 10 jts. Rig crew should have warmed up collars with a hammer before breakin tight connections. Will have to bring more tbg from Lybrook yard in the morning to land tbg. SWIFN. Travel.
7/10/200 9	06:00 - 16:00	10.00	вор	1		Note: Called Bobby Higgins and Four Corners will adjust cost for bent tbg and lost time. Will have rig cost on tommorrows report Tbg.Size: 2-3/8" Csg.Size: 4-1/2" Perf: 5658' to 5864' On 7/10/2009 Hold safety meeting. Blow down well. TIH with tbg. NDBOP. Land tbg in hanger with bottom of tbg at 5839.96' KB. RDSU. Clean up location. Tubing Detail: 180 jts 2-3/8" 4.7# J55 8rd = 5794.12'. 1 SN 1.10' 1 jt 2-3/8" w/collar on bottom 32.74' KB 12.00' Total 5839.96' KB
·						Tbg.Size: 2-3/8" Csg.Size: 4-1/2" SITP: 25, SICP: 60 Perfs. 5658' to 5864'