

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-031-07025
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other INJECTION WELL		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator NACOGDOCHES OIL AND GAS, INC.		6. State Oil & Gas Lease No. 306166
3. Address of Operator P.O. BOX 632418, NACOGDOCHES, TX 75963		7. Lease Name or Unit Agreement Name HOSPAH SAND UNIT
4. Well Location Unit Letter _____ E : <u>3640</u> feet from the <u>SOUTH</u> line and <u>1000</u> feet from the <u>WEST</u> line Section <u>1</u> Township <u>17N</u> Range <u>9W</u> NMPM County <u>McKINLEY</u>		8. Well Number 61
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6999' GR		9. OGRID Number 256689
		10. Pool name or Wildcat HOSPAH UPPER SAND

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: INJECTION WELL CLEANOUT ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RIH with 1" tubing and tag sand. Wash sand out to casing TD. Pump 100 gallons of 7.5% HCL, displace with clean formation water. Circulate precipitants out of wellbore. Place well back for injection. Tubing and packer will not be altered during this procedure.

Spud Date:

Rig Release Date:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Dehnisch TITLE VP of Operations DATE 7/28/29

Type or print name Michael Dehnisch E-mail address: mike.dehnisch@nogtx.com PHONE: 936-560-4747

**For State Use Only**

APPROVED BY: Kelly G. Rolt TITLE Deputy Oil & Gas Inspector, DATE AUG 04 2009  
District #3

Conditions of Approval (if any): NOTIFY NMOC D AZTEC 24 HOURS PRIOR TO BEGINNING WORK

By