Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

OMB No 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. Manage in

NM 40645 If Indian, Allottee, or Tribe Name

٠		
	If Unit or CA.	Agreement Name and/or No.

SUBMIT IN TRIPLICATE - Other Instructions on reverse side.			If Unit or CA. Agreement Name and/or No.		
1. Type of Well Oil Well Gas Well Other			Well Name and No.		
2 Name of Operator			Ribeyowids Federal 2 #16		
Black Hills Gas Resources			9. API Well No.		
3a. Address	3b. Phone No. (include area code)	L	30-039-23554		
3200 N 1st Street PO Box 249 Bloomfield, NM 87413 505-634-1111 ext 28			Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Blanco MV, Gavilan PC		
860' FSL & 990' FEL SE/4 SE/4 Section 2 T25N R2W Unit P			County or Parish, State		
			Rio Arriba, New Mexico		

				111100,11011 11101100			
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Production (Start/ Resume)	Water Shut-off			
	Altering Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	Other			
	Change Plans	X Plug and abandon	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal				

Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertunent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/BlA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources (BHGR) intends to Plug and Abandon (P&A) the Ribeyowids Federal 2 #16. Please find BHGR's attached P&A procedure.

> RCVD AUG 6'09 OIL CONS. DIV. DIST. 3

14. I hereby certify that the foregoing is true and correct.	•				
Name (Printed/ Typed)					
Daniel Manus	Title		Regulatory Technician		
Signature Lawel Manns	Date	luly.	30, 200	29	
THIS SPACE FOR FEL	DERAL OR ST	ATE OFFIC	CE USE		
Original Signed: Stephen Mason					1110 - 1 2002
Approved by	Title			Date	AUG 0 4 2009
Conditions of approval, if any are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations the					
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a cr			willfully to make	any departi	nent or agency of the United

(Instructions on page 2)



GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this

form and the number of copies to be submitted, particularly with regard to local area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13 - Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well and date well site conditioned for final inspection looking to approval of the abandonment.

NOTICE

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq , 25 U.S.C 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as requited by 43 CFR 3162.4-1(c); and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to

appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3 - 2, 3162.3 - 3, 3162.3 - 4.

The Paperwork Reduction Act of 1995 (44 U.S C. 3501 et seq.) requires us to inform you that:

This information is being collected to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases

Response to this request is mandatory.

BLM would like you to know that you do not have to respond to this or any other Federal agency -sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT

Public reporting burden for this form is estimated to average 25 minutes per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau information Collection Clearance Officer, (WO-630), Mail Stop 401 LS, 1849 C St., N.W., Washington D.C. 20240

meanth of the things

1 : 1 : 1 : 1

PLUG AND ABANDONMENT PROCEDURE

October 10, 2008

Ribeyowids #2-16

Blanco Mesaverde / Gavilan Pictured Cliffs 860' FSL & 990' FEL, SE, Section 2, T25N, R2W Rio Arriba County, New Mexico, API #30-039-23554 _at N. ______ / Long W.

	Lat N / Long W					
Note:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 14.8 ppg with a 1.18 cf/sx yield.					
1.	This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.					
2.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.					
3.	Rods: Yes X , No , Unknown Tubing: Yes X , No , Unknown , Size 2.375" , Length 5884' Packer: Yes , No X , Unknown , Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.					
4.	Plug #1 (Dakota / Gallup perforations and tops, 6689' ~ 6589'): TIH and tag cement at					

 Plug #1 (Dakota / Gallup perforations and tops, 6689' - 6589'): TIH and tag cement at 6689'. Mix and pump 17 sxs Class B cement above CR and cement to the Dakota/ Gallup intervals. TOH with tubing.

52801

- 4. Plug #2 (Mesaverde perforations and top, 5741' 5329'): PUH and TIH with 5.5" cement retainer, set at 5741'. Load casing above the CR with water and circulate well clean. Pressure test tubing to 1000 PSI. Mix and pump \$6 sxs Class B cement above CR to isolate Mesaverde perforations and cover the Mesaverde top. TOH with tubing.
- 5. Plug #3 (Pictured Cliffs perforations, Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 3506' 3075'): PUH and TIH with 5.5" cement retainer, set at 3506'. Load casing above the CR with water and circulate well clean. Pressure test casing to 800#. If casing does not test, spot or tag subsequent plugs as appropriate. Mix and pump 55 sxs Class B cement above CR to isolate PC interval and cover the Fruitland, Kirtland and Ojo Alamo tops. PUH.

 2/31'

 1231'
- 6. Plug #4 (Nacimiento top, 2462' 2362'): Mix and pump 17 sxs Class B cement inside casing to cover the Nacimiento top. TOH with tubing.
- 7. Plug #5 (9.625" Surface casing, 327' 0'): Perforate 3 squeeze holes at 327'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 120 sxs Class B cement and pump down the 5.5" casing to circulate good cement out bradenhead. Shut in well and WOC.

8. ,	ND cementing valves and cut off wellhead. Fill 5.5" casing with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.	es and cut off wellhead. Fill 5.5" casing with cement as necessary.	nstall

Ribeyowids #2-16

Current

Blanco Mesaverde / Gavilan Pictured Cliffs

860' FSL, 990' FEL, Section 2, T-25-N, R-2-W, Rio Arriba County, NM / API #30-039-23554

Lat N. _____/ Long W. ____

12.25" hole

Today's Date: 10/10/08

Spud: 12/7/84

DK/GI Comp: 2/4/85
DK/GI P&A: 1997
Nac Comp: 1/8/97
Nac P&A: 2/3/97
MV Comp: 1/6/97
PC Comp: 1/8/97
Elevation: 7432' GI
7444' KB

Nacimiento @ 2412'

Ojo Alamo @ 3125'

Kirtland @ 3410' *est

Fruitland @ 3466' *est


Pictured Cliffs @ 3556'

Mesaverde @ 5379'

Gallup @ 6735'

Dakota @ 7944'

7.875" hole



9.625" 36# Casing set @ 277'
Cement with 159 cf (Circulated to Surface)

TOC @ 1900' (T.S.)

Nacimiento Perforations: 2649' – 2663', sqz'd w/84 cf cmt (1997)

2.375" tubing at 5884'
(188 joints, N-80, SN, pinned collar and rods and pump)

Pictured Cliffs Perforations:

3556' - 3578'

DV Tool @ 3811' Cement with 350 sxs (428 cf)

TOC @ DV Tool (Calc,75%)

Mesaverde Perforations:

5791' - 5799'

DV Tool @ 6129' Cement with 475 sxs (583 cf)

TOC @ DV Tool (Calc,75%)

Set CIBP @ 6707; w/2 sxs cement (1997)

Gallup Perforations:

6784' - 7547'

Dakota Perforations:

7950' -- 8086'

5.5",17#, 23#,N-80 Casing set @ 8162' Cement with 450 sxs (567 cf),

TD 8176' PBTD 8124'

Ribeyowids #2-16

Proposed P&A

Blanco Mesaverde / Gavilan Pictured Cliffs

860' FSL, 990' FEL, Section 2, T-25-N, R-2-W,

Rio Arriba County, NM / API #30-039-23554 / Long W.

12.25" hole

Today's Date: 10/10/08

Spud: 12/7/84

DK/GI Comp: 2/4/85 DK/GI P&A: 1997 Nac Comp: 1/8/97 Nac P&A: 2/3/97 MV Comp: 1/6/97 PC Comp: 1/8/97 Elevation: 7432' GI 7444' KB

Nacimiento @ 2412'

Ojo Alamo @ 3125'

Kirtland @ 3410' *est

Fruitland @ 3466' *est


Pictured Cliffs @ 3556'

Mesaverde @ 5379'

Gallup @ 6735'

Dakota @ 7944'

7.875" hole



TD 8176' **PBTD 8124**'

9.625" 36#, Casing set @ 277' Cement with 159 cf (Circulated to Surface)

Perforate @ 327'

Plug #5: 327' - 0' Class B cement, 120 sx

TOC @ 1900' (T.S.)

Plug #4: 2462' - 2362' Class B cement, 17 sxs

Nacimiento Perforations: 2649' - 2663', sqz'd w/84 cf cmt (1997)

> Plug #3: 3506' - 3075' Class B cement, 55 sxs

Cmt Retainer @ 3506'

Pictured Cliffs Perforations: 3556' - 3578'

DV Tool @ 3811' Cement with 350 sxs (428 cf)

TOC @ DV Tool (Calc,75%)

Cmt Retainer @ 5741'

Plug #2: 5741' - 5329' Class B cement, 53 sxs

Mesaverde Perforations:

5791' - 5799'

DV Tool @ 6129' Cement with 475 sxs (583 cf)

TOC @ DV Tool (Calc,75%)

Set CIBP @ 6707' w/2 sxs cement (1997)

Gallup Perforations:

6784' - 7547'

Plug #1: 6689' - 6589'

Class B cement, 17 sxs

Dakota Perforations:

7950' - 8086'

5.5",17#, 23#,N-80 Casing set @ 8162' Cement with 450 sxs (567 cf),

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 2-16 Ribeyowids Federal

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Mesaverde plug to 5280'.
- b) Place the Nacimiento plug from 2131' 2031'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.