RECEIVED

Form 3160-5 (April 2004)	UNITED STATES DEPARTMENT OF THE INTERIOR SEP 10 20			SEP 10 2009	FORM APPROVITY ON B No 1004-0137 Lypnes March 31, 2007		
		BURLAU OF LAND MANA			5 Lease Serial No		
,	Do not use th	NOTICES AND REP nis form for proposals to ell. Use Form 3160-3 (A	drill or to re-	enter an	##### N19787 ##################################		
S	UBMIT IN TR	IPLICATE- Other instr	uctions on reve	rse side.	7 If Unit or CA/Agreement, Name and/or No		
I lype of W	ell Oil Well' (1)	8. Well Name and No.					
2 Name of Ope	erator Maralex Res	Dome Federal 17-27-13 #2 9. API Well No.					
3a. Address P.O. Box 338, Ignacio, CO 81137			3b Phone No <i>(mchide area code)</i> 970-563-4000		30-045-23402 10 Field and Pool, or Exploratory Area		
		F. R. M. or Survey Description)	, , , , , , , , , , , , , , , , , , , ,	THE ALL AL AVERTING AVERT LAWS A	WAW Fruitland Sand PC		
830' FSL ar	nd 830' FWL, Secti	11 County or Parish, State					
		San Juan County, NM					
	12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT⊎I	RE-OF-NOTICE; 1	REPORT, OR OTHER DATA		
TYPE OF	SUBMISSION						
✓ Notice of Subseque	Intent ent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (S Reclamation Recomplete	tart/Resume)		
	andonment Notice	Change Plans	Plug and Abandon	Temporarily A	· · · · · · · · · · · · · · · · · · ·		
		Convert to Injection	Plug Back	Water Disposa			
Attach the following testing has determine	cosal is to deepen dire Bond under which't completion of the inv s been completed. Fir d that the site is ready	ectionally or recomplete horizontally the work will be performed or provided operations. If the operation in all Abandonment Notices shall be for final inspection.)	/, give subsurface location the the Bond No on file esults in a multiple com filed only after all require	ons and measured and to with BLM/BIA. Requi- pletion or recompletion ements, including reclai	any proposed work and approximate duration thereof, rue vertical depths of all pertinent markers and zones ired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has		
Marale	x intends to plug a	nd abandon the Dome Federal	17-27-13 #2 well. Th	e work procedure is	s as follows:		
2. Pull 3. Pum 4. Cut e 5. Back	off well 6' below su	doned well marker. ***Note:			in a field where they may not want a marker		
Attache	d is a wellbore dia	gram.	kor.	1// 1	RCVD SEP 18 '09'		
lule 19.14	5.25,10C	Below ground	marker we	dedon To	Solver Cas III CITED DIA		
all	intermation elplate	atleast3 bel	lay Surface	2.	RCVD SEP 18'09 Surface Casing with his of the surface of stends of the surface of		
14. Thereby o	certify that the fore	going is true and correct	1				
Ivaliie (1	Doris K. Ney)	Title I	Production Technolo	ogist		
Signature	Lh.	wk M	Date		09/09/2009		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false frictitious or fraudulent, statements or representations as to any matter within its jurisdiction.

litle

Office

SEP 1 6 2003

Date

(Instructions on page 2)

Original Signed: Stephen Mason


Approved by

Conditions of approval, if any, are attached Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

Wellbore Diagram

Well:	Dome Fed 17-27-13 #2	Elev	6067' GL (? KB)
Company	Maralex Resources, Inc	Drawn By	D Jeremy Golob
Location:	830' FSL, 830' FWL Sec 17, T27N, R13W San Juan County, NM	Updated	9/2/09



2-7/8" 6.5# casing Set @ 1491', 5" hole TD @ 1509' Cemented w/ 175 sks to surface