

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED **OCT 02 2009**
OMB No. 1004-0135
Expires July 31, 2010

5. Lease Serial No.

SF -078201

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Florance 21A

9. API Well No.

30-045-22117

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

11. County or Parish, State

San Juan County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

925' FNL & 2038' FWL NENW Sec 1 T29N & R09W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Casing Repair ☐ New Construction ☐ Recomplete ☒ Other **Re-perf MV**
☐ Change Plans ☐ Plug and Abandon ☐ Water Disposal
☐ Convert to Injection ☐ Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

09/10/09 RU AWS 840. Press Tst BOP to 1500# high & 200# log; Charted Test O.K.

09/11/09 chk press on well @ 130 Csg 30# Tbg, bled Csg off slowly to bd tank. Pull Tbg.

09/14/09 C/O to 4847'. Circ Dry

09/15/09 Chk press on well @ 130#; blw well DN slowly to BD tnk. TIH tag snd @4410'. RU Tbg Swvl; brk circ w/air mist. C/O to 4877'.

09/16/09 TIH w/3.125" gun & re-perf MV 4680' - 4690'; 4700' - 4710'; 4720' - 4730'; 4740' - 4750' @ 2 JSPF.

TIH land 2 3/8"; J-55; 4.7# Tbg @4765'. RD MO location.

(Interim perfs)

**RCVD OCT 7 '09
OIL CONS. DIV.**

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Cherry Hlava

Title **Regulatory Analyst**

DIST. 3

Signature *Cherry Hlava*

Date **09/29/2009**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

OCT 05 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD