RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR RURE ALL OF LAND MANAGEMENT

OCT 28 2009

Sundry Notices and Reports on Wells		
Sundry Notices and Reports on Wells		ireau of Land Management Farmingian Field (୨୩୧ର
	5.	Lease Number SF - 078995
Type of Well GAS	6.	If Indian, All. or Tribe Name
Name of Operator	7.	Unit Agreement Name San Juan 31-6 Unit
CONOCOPHILLIPS COMPANY 3. Address & Phone No. of Operator	- 8.	Well Name & Number San Juan 31-6 Unit 44
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4. Location of Well, Footage, Sec., T, R, M Surf: Unit H (SENE), 2425' FNL & 1020' FEL, Section 29, T31N, R6W, NMPM	_	30-039-23199
	10.	Field and Pool
	11.	Blanco MV County and State Rio Arriba Co., NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, O	THER I	DATA
Type of Submission Type of Action Notice of Intent Abandonment Change of Plans Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturing	<u>X</u>	Other - Repair tubing
Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		
3. Describe Proposed or Completed Operations 19/03/2009 -09/08/2009 MIRU AWS 473. ND WH NU BOP. Test BOP – good test. TOOH w/t 19/08/2009 – 09/14/2009 Fished retrieved to 4188'. Worked stuck tbg pulling to 60K. Could no		ck the @ 3062'.
nd shot off tbg @ 6643'. RD WL. POOH LD fish from 6643'. 9/15/2009 Con't to fish. 9/17/2009 Tagged on fish @ 6643'. 9/24/2009 - 09/25/2009 RU WL attempted to fish went inside with cutter 6651' cutter stuck. Prop of fish 6643' M/O 6651' Circ. C/O. 9/25/09 Made call to Jim Lovato (BLM) & Kelly Roberts (OCD) Verbal approval to leave fish and put 100' of cmt on top. Permission to TA DK. 9/28/2009 - 10/01/2009 RIH CIBP jarring motion caused plug to set @ 32'. RIH w/Mill. Mill. 0/05/2009 RU Blue Jet WL RIH w/CIBP & set @ 6600'. RD WL. RIH & tagged @ 6600'. Pur on top of CIBP @ 6600'. 0/06/2009 Tagged cmt @ 6548' received verbal from BLM & OCD to proceed. 0/06/2009 RIH w/184 jts, 2 3/8," 4.70#, J-55 tbg & set @ 5799'. ND BOP NU WH. PT tbg for 0/07/2009.	POOH was in hole ed out Comped 10	g. Rig up WL run jet cutter /cutter. RIH w/mill tagged and set a CIBP @ 6600' CIBP @ 32'. lex type III cmt (1.37 cb/sk).
nd shot off tbg @ 6643'. RD WL. POOH LD fish from 6643'. 9/15/2009 Con't to fish. 9/17/2009 Tagged on fish @ 6643'. 9/24/2009 - 09/25/2009 RU WL attempted to fish went inside with cutter 6651' cutter stuck. Proportion of fish 6643' M/O 6651' Circ. C/O. 9/25/09 Made call to Jim Lovato (BLM) & Kelly Roberts (OCD) Verbal approval to leave fish and put 100' of cmt on top. Permission to TA DK. 9/28/2009 - 10/01/2009 RIH CIBP jarring motion caused plug to set @ 32'. RIH w/Mill. Mill. 0/05/2009 RU Blue Jet WL RIH w/CIBP & set @ 6600'. RD WL. RIH & tagged @ 6600'. Put on top of CIBP @ 6600'. 0/06/2009 Tagged cmt @ 6548' received verbal from BLM & OCD to proceed. 0/06/2009 RIH w/184 jts, 2 3/8," 4.70#, J-55 tbg & set @ 5799'. ND BOP NU WH. PT tbg for 0/07/2009.	POOH was in hole ed out Comped 10	g. Rig up WL run jet cutter /cutter. RIH w/mill tagged and set a CIBP @ 6600' CIBP @ 32'. lex type III cmt (1.37 cb/sk). - held. RD RR on RCVD NOV 3 '09 OIL CONS. DIV. DIST. 3
nd shot off tbg @ 6643'. RD WL. POOH LD fish from 6643'. 10/15/2009 Con't to fish. 10/17/2009 Tagged on fish @ 6643'. 10/24/2009 – 09/25/2009 RU WL attempted to fish went inside with cutter 6651' cutter stuck. Prop of fish 6643' M/O 6651' Circ. C/O. 10/25/09 Made call to Jim Lovato (BLM) & Kelly Roberts (OCD) Verbal approval to leave fish and put 100' of cmt on top. Permission to TA DK. 10/28/2009 – 10/01/2009 RIH CIBP jarring motion caused plug to set @ 32'. RIH w/Mill. Mill. 10/05/2009 RU Blue Jet WL RIH w/CIBP & set @ 6600'. RD WL. RIH & tagged @ 6600'. Pure ntop of CIBP @ 6600'. 10/06/2009 Tagged cmt @ 6548' received verbal from BLM & OCD to proceed. 10/06/2009 RIH w/184 jts, 2 3/8," 4.70#, J-55 tbg & set @ 5799'. ND BOP NU WH. PT tbg for 50/07/2009. 14. I hereby certify that the foregoing is true and correct. 15 igned 16	POOH was in hole ed out Comped 10	g. Rig up WL run jet cutter /cutter. RIH w/mill tagged and set a CIBP @ 6600' CIBP @ 32'. Isx type III cmt (1.37 cb/sk). - held. RD RR on RCVD NOV 3 '09 OIL CONS. DIV. DIST. 3
nd shot off tbg @ 6643'. RD WL. POOH LD fish from 6643'. 9/15/2009 Con't to fish. 9/17/2009 Tagged on fish @ 6643'. 9/24/2009 – 09/25/2009 RU WL attempted to fish went inside with cutter 6651' cutter stuck. P op of fish 6643' M/O 6651' Circ. C/O. 9/25/09 Made call to Jim Lovato (BLM) & Kelly Roberts (OCD) Verbal approval to leave fish and put 100' of cmt on top. Permission to TA DK. 9/28/2009 – 10/01/2009 RIH CIBP jarring motion caused plug to set @ 32'. RIH w/Mill. Mill 0/05/2009 RU Blue Jet WL RIH w/CIBP & set @ 6600'. RD WL. RIH & tagged @ 6600'. Put on top of CIBP @ 6600'. 0/06/2009 Tagged cmt @ 6548' received verbal from BLM & OCD to proceed. 0/06/2009 RIH w/184 jts, 2 3/8," 4.70#, J-55 tbg & set @ 5799'. ND BOP NU WH. PT tbg for 0/07/2009. 4. I hereby certify that the foregoing is true and correct. Signed	POOH was in hole ed out Comped 10	g. Rig up WL run jet cutter /cutter. RIH w/mill tagged and set a CIBP @ 6600' CIBP @ 32'. lex type III cmt (1.37 cb/sk). - held. RD RR on
nd shot off tbg @ 6643'. RD WL. POOH LD fish from 6643'. 9/15/2009 Con't to fish. 9/17/2009 Tagged on fish @ 6643'. 9/24/2009 – 09/25/2009 RU WL attempted to fish went inside with cutter 6651' cutter stuck. Prop of fish 6643' M/O 6651' Circ. C/O. 9/25/09 Made call to Jim Lovato (BLM) & Kelly Roberts (OCD) Verbal approval to leave fish and put 100' of cmt on top. Permission to TA DK. 19/28/2009 – 10/01/2009 RIH CIBP jarring motion caused plug to set @ 32'. RIH w/Mill. Mill. 10/05/2009 RU Blue Jet WL RIH w/CIBP & set @ 6600'. RD WL. RIH & tagged @ 6600'. Pur op of CIBP @ 6600'. 10/06/2009 Tagged cmt @ 6548' received verbal from BLM & OCD to proceed. 10/06/2009 RIH w/184 jts, 2 3/8," 4.70#, J-55 tbg & set @ 5799'. ND BOP NU WH. PT tbg for 0/07/2009. 4. I hereby certify that the foregoing is true and correct. Signed Jamie Goodwin Title Regulatory Technology. This space for Federal or State Office use)	POOH was in hole ed out Comped 10	g. Rig up WL run jet cutter /cutter. RIH w/mill tagged and set a CIBP @ 6600' CIBP @ 32'. /ex type III cmt (1.37 cb/sk). - held. RD RR on