Bill Richardson

Joanna Prukop Cabinet Secretary Mark Fesmire
Division Director
Oil Conservation Division



November 3, 2009

Cherry Hlava B P America PO Box 3092 Houston TX, 77253

Re: Valentine Gas Com #1M, C-32-32N-10W, API # 30-045-33218

Dear Ms. Hlava:

The 2009 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before February 8, 2010.

Intermediate casing pressure of 1000 psi was noted. The intermediate casing had a strong steady flow throughout the test and a five minute shut in pressure of 420 psi.

With your sundry please attach a copy of the last two Bradenhead test reports, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top and provide gas analysis from all casing strings.

Reference: RBDMS KGR0930630621 on future correspondence for this matter.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly G. Roberts

Deputy Oil & Gas Inspector

District III-Aztec

CC: Well File

