<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

side of form

Form C-141

Revised October 10, 2003

## **Release Notification and Corrective Action**

				(	PERATOR		🛛 Initial I	Report	☐ Final Report	
Name of Co	mpany	Conoco	Phillips		Contact		Gwen R. Frost			
Address			<u>, Farming</u>	ton, NM 8740						
Facility Name Sooner #1					Facility Type			API # 30-039-26665		
Surface Owner Federal Mineral Owner				ner <b>Federa</b>		Leas	Lease No. <b>NM-93252</b>			
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the				ine Cour		
F 21 T26N R07W 1530'				North	1565'	West	West Rio Arriba			
Latitude <u>36.47501 ° N</u> Longitude <u>107.58424 ° W</u>										
NATURE OF RELEASE										
Type of Relea									Volume Recovered – <b>0 BBL</b>	
				on water pit					Hour of Discovery	
tank poss			on			6-17-09 6/18/09 –9:00 a.m.			–9:00 a.m.	
Was Immedia	ite Notice G		s 🗆 No	☐ Not Require		If YES, To Whom?  OCD - Brandon Powell via phone call & e-mail				
·			.3 📙 140	Not Require	1	Kevin Schneider via phone call & e-mail				
By Whom? Gwen Frost						Date and Hour - 6/18/09 - 4:00 p.m. PCUD JUN 24 '03				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.  OIL CONS. DIV.				
			Yes 🛛 I	No					UHJ. DIV.	
If a Watercou	rse was Imp	oacted, Descr	ibe Fully.*			DIST. 3				
Describe Cause of Problem and Remedial Action Taken.* On June 18, 2009, approximately 40 BBLS of produced water was										
released due to a spilt bottom side seam on the water pit tank possibly due to corrosion. All fluid remained on										
location in the berm. Upon discovery, COPC shut down the water dump & B-valve.										
Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm and no water was										
recovered. A sample of the soil was collected & clean-up will be determined based on analytical results. To prevent reoccurrence, COPC will continue to monitor tanks for leaks.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
Traditit, State,						OIL CONSERVATION DIVISION				
Signature:	Hu	en R. Fr	180			<u> </u>			<u> </u>	
									, For: Charlie Perrin	
Timed Ivalle								- o w	remin	
Title:	Env	ironmenta	l Enginee	r	Approval Date	:6/24/0°	Expirati	ion Date:		
E-mail Addre	ss: <b>gwenc</b>	lolynne.fro	ost@cono	cophillips.co	<u>n</u> Conditions of	Approval:		Attac	ched	

\* Attach Additional Sheets If Necessary

Phone: 505-326-9549

6/19/09

Incident # 11 km D 0925235931