

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

API # 30-039-23242

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Huntington Energy, L.L.C.	Contact	Alan McNally
Address	908 N.W. 71 <sup>st</sup> St., Oklahoma City, OK 73116	Telephone No.	405-840-9876
Facility Name	Canyon Largo Unit #327	Facility Type	Tank Battery

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	Lease No. E-29137
------------------------------------	------------------------------------	-------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	32	25N	6W	790	South	1850	East	Rio Arriba

Latitude 36.35126 Longitude -107.48769

**NATURE OF RELEASE**

Type of Release	Crude Oil/Produced Water	Volume of Release	240 bbls	Volume Recovered	156 bbls
Source of Release	Stock Tank	Date and Hour of Occurrence:	1:00 am, 2/6/09	Date and Hour of Discovery	8:30 am, 2/6/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM Office, Alfonso Atencio		
By Whom?	David Morales	Date and Hour	8:30 am, 2/6/09		
Was a Watercourse Reached? (Dry Sand)	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	Est, 20-25 bbls		

If a Watercourse was Impacted, Describe Fully.\*  
Path of contents extended approx. 250-300 yds, approximately 3' wide and narrowing down to 1 ft. in Sandy Arroyo

RCVD FEB 17 '09  
OIL CONS. DIV.  
DIST. 3



Describe Cause of Problem and Remedial Action Taken.\*

Freeze occurred in the threads of ball valve on load line of stock tank causing an expansion and a release of the contents in the stock tank.  
Action taken: Immediate notification. Call for equipment. Valve replaced.

Describe Area Affected and Cleanup Action Taken.\*

Dike area 4' wide path to road, spreading out to 12' to Arroyo narrows down to 3'-1' traveling approximately 250 yds-300 yds. Cleanup-vacuum all possible fluid, excavate all area impacted immediately. All operations approved by BLM. BLM representative on location to assess clean-up and any further instructions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Alan McNally	Approved by District Supervisor: 		For: Charlie Perrin
Title: Engineer	Approval Date: 2-17-09	Expiration Date:	
E-mail Address: amcnally@huntingtonenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 2/13/2009	Phone: 405-840-9876 ext. 136		

\* Attach Additional Sheets If Necessary

NBP0918937817