<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

Release Notification and Corrective Action

OPERAT						RATOR Initial Report Final Report		
Name of Company ConocoPhillips Company					Contact	Kristina	Kristina Kovach	
Address 3401 E. 30 th St., Farmington, NM 87402					Telephone N			
Facility Name San Juan 28-7 Unit #145G					Facility Typ			API # 30-039-26989
Surface Owner Federal Mineral Owner					Feder	Federal Lease No. SF-078972		
LOCATION OF RELEASE								
Unit Letter	Section	Township	Range		h/South Line	Feet from the	East/West Line	1 7
L	10	T27N	R7W	2050'	South	880'	West	Rio Arriba
Latitude 36.58684 ° N Longitude 107.56775 ° W								
NATURE OF RELEASE								
Type of Release – Condensate								Volume Recovered – none
Source of Release: Tank leak due to corrosion								Date and Hour of Discovery 4/28/08 – 1:15 p.m.
Was Immediate Notice Given?					If YES, To Whom?			
✓ Yes ☐ No ☐ Not Required					OCD - Brandon Powell via phone & email			
·					BLM - Kevin Schneider via email			
By Whom? Kristina Kovach					Date and Hour – 4/29/08 – 10:00 a.m. KCVU MHY 12 US			
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*								Midf. d
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips Company employee discovered a condensate spill of approximately 75 BBL at the San Juan 28-7 Unit #145G on the afternoon of 4/28/08 due to a leak in the condensate tank. The release was due to small holes in the bottom of the tank that resulted from corrosion. Upon discovery, the well was shut in and the remaining oil was transferred to another production tank. Describe Area Affected and Cleanup Action Taken.* The spilled fluids were contained within the berm. No fluids were recovered. The tank will be replaced, and the affected soils will be excavated from under the tank. To prevent reoccurrence, COPC will continue to perform a monthly inspection of tanks. The Asset & Operating Integrity Department will review corrosion prevention methods for the equipment on this well.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
Signature: Rustina L. Koroch					Approved by District Supervisor:			
Printed Name: Kristina L. Kovach					Approved by District Supervisor: For: Charlie Perrin			
Title:		/ironmenta		ate	Approval Dat	e: 5/12/08	Expiration	
E-mail Address: kristina.l.kovach@conocophillips.com					Conditions of	Conditions of Approval:		
Date: 5	/5/08		Phone: 5()5-326-9866				

Incident # n Rmb 0929 649 007