

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-039-82247

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Benson-Montin-Greer Drilling Corp.	Contact Mike Dimond
Address 49 College Blvd	Telephone No. 505-325-8874
Facility Name East Puerto Chiquito Mancos Unit #14 N-19	Facility Type - Well Location

Surface Owner Jicarilla Apache Nation	Mineral Owner Jicarilla Apache Nation	Lease No. Jic. 237
---------------------------------------	---------------------------------------	--------------------

LOCATION OF RELEASE

Unit Letter N	Section 19	Township 27N	Range 1E	Feet from the	North/South Line 660' FSL	Feet from the	East/West Line 1980' FWL	County Rio Arriba
------------------	---------------	-----------------	-------------	---------------	------------------------------	---------------	-----------------------------	----------------------

Latitude 36.53213 Longitude -106.87085

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 bbls.	Volume Recovered 7 bbls
Source of Release Gathering line tie-in at location	06/11/09 early morning	6/11/09 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bryce Hammond with BLM - Jicarilla Office was on location when discovered	
By Whom? Ben Gonzales	Date and Hour 06/11/09 7:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD JUN 16 '09
OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.*

The well was being plugged and had been disconnected from gathering line. Apparently a cow kicked open the valve on the line and oil spilled from the line. Extensive rain in area kept spill on surface. Crude was vacuumed with water truck (7bbls), mopped with absorbent pads, and any contaminated soil will be scraped from surface (estimate 5 Cu. Yds.) and removed to BMG Landfarm. Soil scraping cannot be done until Mr. Gifford Velarde, Jicarilla approved archeologist clears site on Monday, June 15, 2009. Will schedule soil sampling for Wednesday, June 17 or after.

Describe Area Affected and Cleanup Action Taken.*

Approximately 10' x 50' area on location and two 2' x 75' areas north of location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mike Dimond</i>	OIL CONSERVATION DIVISION	
Printed Name: Mike Dimond	Approved by District Supervisor: <i>Brandon Bell</i> For: <i>Charlie Perrin</i>	
Title: President	Approval Date: 6-16-09	Expiration Date:
E-mail Address: mikedimond@bmgdrilling.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 12, 2009	Phone: 505-324-5069	

* Attach Additional Sheets If Necessary

Incident # NRMD0924742365

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Benson-Montin-Greer Drilling Corp.	Contact Mike Dimond
Address 49 College Blvd	Telephone No. 505-325-8874
Facility Name East Puerto Chiquito Mancos Unit #14 N-19	Facility Type - Well Location

Surface Owner Jicarilla Apache Nation	Mineral Owner Jicarilla Apache Nation	Lease No. Jic. 237
---------------------------------------	---------------------------------------	--------------------

LOCATION OF RELEASE

Unit Letter N	Section 19	Township 27N	Range 1E	Feet from the	North/South Line 660' FSL	Feet from the	East/West Line 1980' FWL	County Rio Arriba
------------------	---------------	-----------------	-------------	---------------	------------------------------	---------------	-----------------------------	----------------------

Latitude 36.53213 Longitude -106.87085

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 bbls.	Volume Recovered 7 bbls
Source of Release Gathering line tie-in at location	06/11/09 early morning	6/11/09 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bryce Hammond with BLM - Jicarilla Office was on location when discovered	
By Whom? Ben Gonzales	Date and Hour 06/11/09 7:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The well was being plugged and had been disconnected from gathering line. Apparently a cow kicked open the valve on the line and oil spilled from the line. Extensive rain in area kept spill on surface. Crude was vacuumed with water truck (7bbls), mopped with absorbent pads, and any contaminated soil will be scraped from surface (estimate 5 Cu. Yds.) and removed to BMG Landfarm. Soil scraping cannot be done until Mr. Gifford Velarde, Jicarilla approved archeologist clears site on Monday, June 15, 2009. Will schedule soil sampling for Wednesday, June 17 or after.

Describe Area Affected and Cleanup Action Taken.*

Approximately 10' x 50' area on location and two 2' x 75' areas north of location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Mike Dimond		Approved by District Supervisor:	
Title: President	Approval Date:	Expiration Date:	
E-mail Address: mikedimond@bmgsdrilling.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: June 12, 2009	Phone: 505-324-5069		

* Attach Additional Sheets If Necessary