District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

Name of Company Contacts Systems, Inc. Address P.O. Box 60760, Midland, TX 79711-0760 (915) 493-3155 Facility Name Gonzales Mesa Compressor Station (K-33) Surface Owner BLM Location of Release Location of Release Location of Release Location of Release Type of Release Condensate Tank Spill Source of Release Condensate tank within berno National Advance of Problem and Remedial Action Taken.* By Whom? Natural Gas Compressor Station North PyES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Cause of Problem and Remedial Action Taken.* Tank legalds (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and liken to us appropriate contractor and such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank legalds (consisting of oil ywater) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and liken to us appropriate contractor and liken to		30	039	225	26(OPERA'	TOR		- □ Initi	ial Repor	R 74 (N) Eir	al Report	
Address P.O. Box 60/50, Midland, TX 79711-0760 (915) 495-3155 Facility Type Onzales Mesa Compressor Station (K-33) Mineral Owner Location of Release Unit Letter Section Township 32 26 N 6 W 2150 North No	Name of Company														
P.O. Box 60760, Midland, TX 79711-0760 [915] 495-3155 Facility Type Sharing Gonzales Mesa Compressor Station (K-33) Surface Owner BLM LOCATION OF RELEASE Unit Letter Section Township Range As 25 North/South Line Rent from the Rash West Line County Fast North/South Line Rent from the Rash West Line County Fast Rio Arriba NATURE OF RELEASE Volume of Release Condensate Tank Spill Source of Release Condensate Tank Spill Source of Release Condensate Tank Spill Source of Release Suspected late 16 or early 17 Was Immediate Notice Given? Was Immediate Notice Given? Was a Watercourse Reached? Yes No Not Required N/A By Whom? N/A By Whom? N/A Describe Cause of Problem and Remedial Action Taken.* Improperty closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such than future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleump Action Taken.* Improperty closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such than future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleump Action Taken.* Improperty closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such than future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleump Action Taken.* Improperty closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank and removed when pumping is complete. Describe Area Affected and Cleump Action Taken.* Improperty closed ball valve on outlet of tank line froze and broke overnight, cau								Terry Christian, Environmental Director							
Facility Name Facility Type Facility Typ	1							Telephone No. JAN 2002							
Surface Owner BLM LOCATION OF RELEASE NATURE OF RELEASE NATURE OF RELEASE NATURE OF RELEASE NATURE OF RELEASE Volume Recovered Obbi Obbi Source of Release Condensate Tank Spill Source of Release Condensate Tank within bern Obbi Obtained and Hour of Occurrence Suspected late 1/6 or early 1/7 If YES, To Whom? NA Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully. N/A Describe Cause of Problem and Remedial Action Taken. Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken. Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. Ihereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/off ile certain release notifications and perform corrective actions of releases which may endanger public health or the environment. The addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations OIL CONSERVATION DIVISION Approval Date: The Approval Date: Approvious of the part of the compliance with any other federal, state, or local laws and/or regulations. Approved by Expiration Date:								(913) 493-3133							
Surface Owner BLM LOCATION OF RELEASE NATURE OF RELEASE NATURE OF RELEASE NATURE OF RELEASE NATURE OF RELEASE Volume Recovered Obbi Obbi Source of Release Condensate Tank Spill Source of Release Condensate Tank within bern Obbi Obtained and Hour of Occurrence Suspected late 1/6 or early 1/7 If YES, To Whom? NA Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully. N/A Describe Cause of Problem and Remedial Action Taken. Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken. Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. Ihereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/off ile certain release notifications and perform corrective actions of releases which may endanger public health or the environment. The addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations OIL CONSERVATION DIVISION Approval Date: The Approval Date: Approvious of the part of the compliance with any other federal, state, or local laws and/or regulations. Approved by Expiration Date:								Pacinity Type Natural Gas Compressor Station							
LOCATION OF RELEASE															
Unit Letter Section Township Renge Feet from the North/South Line Feet from the East East East Ro Arriba										_	Lease 1	No.C.	1000		
Unit Letter Section Township Renge Feet from the North/South Line Feet from the East East East Ro Arriba	LOCATION OF RELEASE														
Type of Release Type of Release Type of Release Type of Release Type of	Unit Letter				Feet fro	m the Nort	h/S		Feet from the	1	West Line				
Type of Release Condensate Tank Spill Source of Release Condensate Tank Spill Source of Release Condensate Tank Spill Source of Release Condensate tank within berm Was Immediate Notice Given? Was a Watercourse Reached? Date and Hour N/NA N/A Was a Watercourse Reached? Wes No Was a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of esponsibility for compliance with any other federal, state, or		33	26 N	6 W	2150	Nort	h		1340	East	·	Rio Ari	riba	``	
Source of Release Date and Hour of Occurrence Suspected late 1/6 or early 1/7 Date and Hour of Discovery Date and Hour of Discovery Date and Hour of Discovery 17/02 4:30 pm Date and Hour of Discovery Date and Hour N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. Ihereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the ope															
Source of Release Condensate tank within berm Was Immediate Notice Given? Was a Watercourse Reached? Date and Hour of Occurrence N/A Was a Watercourse Reached? Date and Hour N/A Was a Watercourse Reached? We No If a Watercourse was Impacted, Describe Fully. N/A Describe Cause of Problem and Remedial Action Taken. Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken. Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature A. Approved by District Supervisor: Approved by District Supervisor: Approved by District Supervisor: Approved District Supervisor: Approved Date: DATE A															
Was Immediate Notice Given? Yes No Not Required Not Requi	Source of Release							Date and I							
By Whom? N/A Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of iliability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law for the control pate: Approved by District Supervisor: For Frank Chave Z Title: Environmal Director Ment Approval Date: DA D4/O2 Expiration Date:							_			1/7/02 4:30 pm					
By Whom? N/A Was a Watercourse Reached? If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Approved by Terry Christian Approved by Terry Christian Approved Date: O HOV / O2 Expiration Date:															
Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* N/A								Date and Hour							
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Approved by District Supervisor: Approved by District Supervisor: Approved Date: Approved Date:															
Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Approved by District Supervisor: Or Frank Chavez Approved by District Supervisor: Or Frank Chavez Approved Date: O A O A O A O A Chave Description Date:								If YES, volume impacting the watercourse.							
Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Approved by District Supervisor: Or Frank Chavez Approved by District Supervisor: Or Frank Chavez Approved Date: O A O A O A O A Chave Description Date:															
Describe Cause of Problem and Remedial Action Taken.* Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have falled to adequately investigate and remediate contamination at pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Approved by District Supervisor: For Frank Chavez Title: Environmental Director March Chaves Approved Date: DA OH/O2 Expiration Date:															
Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Formula Director Agent Approved by District Supervisor: For Frank Chave 2 Approved by District Supervisor: For Frank Chave 2 Approved Date: OFFICE Approved Date: Paper and Date: Paper and Date: OFFICE Approved Date	N/A														
Improperly closed ball valve on outlet of tank line froze and broke overnight, causing spillage outside of berm. The valve and line are to be removed from the tank such that future removals will require a hose to be directly hooked to the tank and removed when pumping is complete. Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Formula Director Agent Approved by District Supervisor: For Frank Chave 2 Approved by District Supervisor: For Frank Chave 2 Approved Date: OFFICE Approved Date: Paper and Date: Paper and Date: OFFICE Approved Date	Describe Cause of Problem and Remedial Action Taken *														
Describe Area Affected and Cleanup Action Taken.* Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Approved by District Supervisor: OVER OF MOCD TONSERVATION DIVISION Approved by District Supervisor: OVER OF MOCD TONSERVATION DIVISION Approved by District Supervisor: OND Expiration Date:															
Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by District Supervisor: OIL CONSERVATION DIVISION															
The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Christian Approved by District Supervisor: For Frank Chave 2 Title: Environmental Director Highert Approval Date: OHOMAN Expiration Date:	Describe Area Affected and Cleanup Action Taken.*														
The soil is to be removed by an appropriate contractor and taken to an appropriate landfarm for treatment by 10 January 2002. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Law Christian Approved by District Supervisor: For Frank Chave 2 Title: Environmental Director Highert Approval Date: OHOMAN Expiration Date:	Tank liquids (consisting of oily water) were spilled to soil around the berm. The spill was completely absorbed into the soil, no standing liquid remains														
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by District Supervisor: Title: Environmental Director Agent Approval Date: OHOMAN Expiration Date:															
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION															
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by District Supervisor: Frank Chavez Title: Environmental Director Agent Approval Date: 07/04/02 Expiration Date:															
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by District Supervisor: Frank Chavez Title: Environmental Director Agent Approval Date: 07/04/02 Expiration Date:															
Signature In for Terry Christian Printed Name: Terry Christian Approved by District Supervisor: Frank Chavez Title: Environmental Director Agent Approval Date: 07/04/02 Expiration Date:	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
Printed Name: Terry Christian Printed Name: Terry Christian Approved by Denny Frank Chavez District Supervisor: Frank Chavez Approval Date: 07/04/02 Expiration Date:	federal, state,	, or local la	ws and/or regu	ılations.			·			CERT		DIVITO	10) 1		
Title: Environmental Director HGEN/ Approval Date: 04/07/02 Expiration Date:			1 7	γ .			OIL CON	SEKV	ATION	DIVIS	<u>JON</u>				
Title: Environmental Director HGEN/ Approval Date: 04/07/02 Expiration Date:	Signature Johnshan								Nous Feent						
Title: Environmental Director HGEN/ Approval Date: 04/07/02 Expiration Date:	Printed Name: Terry Christian									F	cenk (-hau	167		
	Title	Envic		2/01/											
					, 010	1100 200		- • • · · ·		102	DAPHALION		ned []		
Date: U Jan 'O' Phone: (915) 495. 315 Conditions of Approval: Attach Additional Sheets If Necessary ND(-1070) 35.3 72.57				Phone:	(915	1475 . 2131	\ V			770	11	71114011			