<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

Release Notification and Corrective Action

OP					PERATOR		Initial 1	Report Final Report	
Name of Company ConocoPhillips Company					Contact		Monica D. Johnson		
Address 3401 E. 30 th St., Farmington, NM 87402					Telephone No		505-326-9829		
Facility Name San Juan 29-6 Unit #301 SWD				Facility Type	Salt Wat	Salt Water Disposal Well API #30-039-24807			
Surface Owner State Mineral Owner					r State		Lease No. E-289-3		
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West L		
Р	2	T29N	R6W	350'	South	350'	East	Rio Arriba	
Latitude 36.74829° Longitude 107.42384°									
NATURE OF RELEASE									
Type of Relea	ase – Proc	luced wate	r		Volume of Rele	Volume of Release – 8 BBL Volume Recovered – 7 BBL			
Source of Release: Line leak (repeat failure)					Date and Hour 11/25/07	of Occurrence	Date and Hour of Discovery 11/25/07 – 2:30 p.m.		
Was Immediate Notice Given?						If YES, To Whom?			
☐ Yes ☐ No ☒ Not Required					Brandon Powell – OCD – via email				
					Richard Gallegos – NM State Land Office – via email				
By Whom? Monica D. Johnson					Date and Hour – 11/29/07 – 2:30 p.m.				
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.* A contract mechanic discovered a spill of 8 BBL produced water at the San Juan 29-6 Unit #301 SWD on the afternoon of 11/25/07, due to a line leak (repeat failure). The spill occurred when a 10" stainless steel line between the filter pot and the pump developed a leak. Upon discovery, the main inlet to the water transfer station was shut off and the leak was isolated. All fluids remained within the bermed area, and 7 BBL was recovered by vacuum truck. The SWD was shut down for investigation into the repeat failure and the lines were replaced with 10" Schedule 80 pipe instead of flexline. Describe Area Affected and Cleanup Action Taken.* All fluids remained within the bermed area, and 7 BBL was recovered by vacuum truck. The remaining impacted soils were allowed to dry and raked to promote rehabilitation of the soils. The SWD was shut down for investigation into the repeat failure and the lines were replaced with 10" Schedule 80 pipe instead of flexline. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and									
regulations a public health should their or or the environ	II operators or the envi operations h nment. In a	are required ronment. The nave failed to	to report and/ e acceptance of adequately in OCD acceptant	or file certain releas of a C-141 report by evestigate and remed	e notifications and the NMOCD man liate contamination	I perform corrective ked as "Final Report that pose a threa	ve actions for a cort" does not a t to ground wa	pursuant to NMOCD rules and releases which may endanger relieve the operator of liability ater, surface water, human health or compliance with any other	
Signature: Maria ()					1	OIL CONSERVATION DIVISION			
Printed Name: Monica D. Johnson Approved by District Supervisor: Branker For:								For: Charlie Perrin	
Printed Name	e: <u>M</u>	onica D. J	ohnson			4.00		· · ·	
Title:	Sr. E	nvironmen	tal Scienti	st	Approval Date	:11/30/07	Expiration	on Date:	
E-mail Addre	ess: moni	ca.johnsor	<u>@conoco</u>	phillips.com	Conditions of A	Approval:		Attached	
Date: 1	1/29/07		Phone:	505-326-9829					

^{*} Attach Additional Sheets If Necessary