<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 FEB 2002 Revised March 17, 1999

Submit 2-Gopies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action 30 039 26483

	30	039	26	183		OPERAT	OR	- CC	STA S	Report	$\boxtimes$	Final Report	
Name of Company BP America Production Company						Contact Brittany Benko							
Address 200 Energy Court Farmington, NM 87401						Telephone No. (505) 326-9235							
Facility Name Carracas Canyon Unit 36 A #1						Facility Type Wellsite							
Surface Owi	or Fores	wner ]	BLM Lease No. NMNM29340										
Surface Owi	ici rores	DEM Lease INO. INIVITATIVE 2540						·					
· · · · · · · · · · · · · · · · · · ·		_				OF REI							
Unit Letter	Section	Township	Range	Feet from the		South Line			West Line	County			
A	36	32N ,	5W	430	North	Line	800	East	Line	Rio Arriba County		ity	
NATURE OF RELEASE													
T CD.1.	D			NAT	UKE	_			l v I D	1.0			
Type of Release Produced Water											Lecovered 0 bbls Hour of Discovery		
Source of Release Pipeline							Unknown Date and Hour of Occurrence Date and Hou Date and				· · · · · · · · · · · · · · · · · · ·		
Was Immediate Notice Given?							If YES, To Whom?						
		,											
By Whom?							Date and Hour						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*  A produced water line on the well location parted causing the produced water to back flow on the location. The well was shut-in at the time, therefore all water was from the produced water pipeline. The pipeline was isolated near the location. A pumper in the area was immediately dispatched to check all shut-in wells to see if the same problem could develop  Describe Area Affected and Cleanup Action Taken.*													
The produced water soaked in on location. The impacted soil will be landfarmed on site. Repairs on the produced water pipeline will be completed in the spring, which will involve burying the above ground valve.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
_							OIL CONSERVATION DIVISION.						
Signature: Britlan Bliko							1) emy tour						
							Approved by District Supervisor: For Frank Charz						
Frinted Name	· Unt	rany D.	DOIK	υ <u>.</u>									
Title: Flela	Fitle: Fleld Environmental Coordinator A						Approval Date: 02/29/02			Expiration Date:			
Date: 02				326-9235	,	Conditions of	`Approval:			Attached	<u> </u>		
Attach Addit	ional Shee	ets If Necess	ary			n DG	F0205	137	173				