

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-26523

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips	Contact	<input type="checkbox"/> Patsy Clugston
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	<input type="checkbox"/> 505-599-3454
Facility Name	San Juan 30-5 Unit #213R	Facility Type	<input type="checkbox"/> Gas Well

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	<input type="checkbox"/> SF-080066
---------------	-----	---------------	-----	-----------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	5	30N	5W	2629'	North	697'	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	12 bbls	Volume Recovered	<input type="checkbox"/> 10 bbls
Source of Release	Overflowed water tank	Date and Hour of Occurrence	Approx. 10/17/02	Date and Hour of Discovery	<input type="checkbox"/> 1:00 pm 10/17/02
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust - OCD @ 10:00 am 10/18/02 e-mail And Mark Kelly BLM @ 10:00 am 10/18/02 e-mail		
By Whom?	Patsy Clugston	Date and Hour	<input type="checkbox"/> 10/18/02 10:00 am by e-mail		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Watercourse was NOT impacted.

Describe Cause of Problem and Remedial Action Taken.*

It appears the Murphy Gauge malfunctioned, therefore the pump didn't engaged to pump the high liquid level off the tank and down the line.

Describe Area Affected and Cleanup Action Taken.*

Approx. 12 bbls of produced water spilled and all of it was contained within the bermed area around the tank. Approx. 10 bbls of fluid was sucked up by Key and disposed of. There is will be no further clean-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Patsy Clugston</i>	OIL CONSERVATION DIVISION	
Printed Name:	Patsy Clugston	Approved by <input type="checkbox"/> District Supervisor:	<i>Denny Foust</i> for Frank Chavez
Title:	Sr. Regulatory/Proration Clerk	Approval Date:	10/24/02
Date:	October 18, 2002	Phone:	505-599-3454
Conditions of Approval:		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

M DGT 0229740527