<u>District I</u>
1625 N. French Dr , Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003 abmit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR									
Name of Co owned suk				es, a wholly Company	Contact				
Address 3401 E. 30 th St., Farmington, NM 87402					02 Telephone	Telephone No. 505-326-9829			
Facility Nan	ne Sa ı	1 Juan 27-4	Unit #	17P		Facility Type Gas Well API # 30-039-29838			
Surface Own	ner Pri	vate		Mineral Ov	wner Fede	Federal Lease No. SF-080669			
LOCATION OF RELEASE									
Unit Letter H					North/South Line North	Feet from the 170'	East/West Lir East	e County Rio Arriba	
Latitude36.55955°Longitude107.26552°									
NATURE OF RELEASE									
Type of Relea						elease – 10 BBI		Volume Recovered – 8 BBL	
Source of Rel problems			ue to w	ell access	8/6/07	,			
Was Immediate Notice Given?						If YES, To Whom?			
☐ Yes ☐ No ☒ Not Required						Brandon Powell – OCD – via email			
By Whom? Monica D. Johnson						Mark Kelly – BLM – via email Date and Hour – 8/8/07 – 11:00 a.m.			
By Whom?	ourse Read		JUIIISC	7) I		If YES, Volume Impacting the Watercourse.			
Was a Watercourse Reached? ☐ Yes ☒ No						if TES, Volume impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*									
Unit #47P on 8/7/07 by a Dawn Trucking water hauler, due to a 500 BBL produced water tank overfilling when the well could not be accessed because of muddy roads, weather, and poor communication by the water hauler. All fluids were contained on the location in the immediate area of the tank, with 8 BBL recovered by a vacuum truck. Describe Area Affected and Cleanup Action Taken.* All fluids were contained on the location in the immediate area of the tank,									
with 8 BBL recovered by a vacuum truck. For remediation of the remaining impacted soils, an application of "gator									
soaker" was applied.								RCVD AUG 9 '07	
								OIL CONS. DIV. DIST. 3	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
Signature: OIL CONSERVATION OIL CONSERVATION							-		
Printed Name: Monica D. Johnson Approved by District Supervisor: Brandon Pauell								Powell For: Charlie Perrin	
Title: Environmental Specialist Approval Date: 8-9-07 Expiration Date:								ion Date:	
E-mail Address: monica.johnson@conocophillips.com Conditions of Approval:							Attached		
Date: 8	/8/07		Phone: 5	05-326-9829				_	

^{*} Attach Additional Sheets If Necessary