

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street


Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141

Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.



Release Notification and Corrective Action

3004526840

OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9841
Facility Name:	SCOTT: 100	Facility Type:	Cedar Hill SWD Header

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-078604
----------------	---------	----------------	---------	---------------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County:
H	29	032N	010W	1460	North	1150	East	San Juan

NATURE OF RELEASE

Type of Release:	Oil and Produced Water	Volume of Release:	10 BBLs.	Volume Recovered:	0 BBLs.
Source of Release:	SWD Header	Date and Hour of Occurrence:	12/30/2002 3:30:00 PM	Date and Hour of Discovery:	12/30/2002 3:30:00 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?	Denny Foust		
By Whom?		Date and Hour:	12/31/02		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

A valve on the header was left open by a water truck driver. This is the header for the Cedar Hill SWD. A mixture of oil and water leaked out of the valve and traveled approximately 75 yards down a ditch next to the road.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

The impacted soils were excavated and landfarmed on the Scott #100 location. A check valve will be installed to prevent reoccurrence.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Ed Hasely	Approved by	
Title:	Environmental Representative	District Supervisor:	for Frank Chavez
Date:	12/31/02	Approval Date:	1/06/03
Phone:	(505) 326-9841 or 326-9842	Expiration Date:	
Conditions of Approval:		Attached: <input type="checkbox"/>	

NDGF0300229345