District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OP						ERATOR Initial:			Report	⊠ F	inal Report	
Name of Company ConocoPhillips Company						Contact Beverly J. Cox						
Address 3401 E. 30 th St., Farmington, NM 87402						Telephone No. 505-324-6194						
Facility Name San Juan 32 Fed 13-1A						Facility Typ						
Surface Owner Federal Mineral Owner						Feder	Federal Lease No. NMS			IMSF 0	79329	
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	Nort	h/South Line	Feet from the	East/West Lin	e Count			
J	13	32N	9W	1350'		South	1450'	East			Juan	
		Latitud	e 3	6.980530°		Longitude	Longitude -107.726500° RCVD JAN 4 '08					
NATURE OF RELEASE DIST. 3												
						Volume of Release – 45 bbls Volume Recovered – 45 bbls						
Source of Release: equalizing line clamp						Date and Hou	Date and I	Date and Hour of Discovery				
						12/28/07 time unknown 12/28/0				6:30p	m	
Was Immediate Notice Given?						If YES, To Whom?						
☐ Yes ☒ No ☐ Not Required						Brandon Powell – OCD – via phone on 12/31/07						
By Whom? Beverly Cox						Mark Kelly – BLM – via email Date and Hour – 12/31/07 – 10am.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes 🛛 No												
If a Watercourse was Impacted, Describe Fully.*												
No Describe Cause of Problem and Remedial Action Taken.*												
A transfer pump failed causing the produced water tank to fill up and equalize/over flow to the next tank. A clamp on the equalizing line												
froze and started leaking. The tanks were emptied via a vacuum truck. The equalizing line was repaired the next day.												
Describe Area Affected and Cleanup Action Taken.*												
The ground was frozen allowing the ability to vacuum all produced water that was released to the ground. No remediation required.												
I haraby carti	fy that the	nformation a	van abov	e is true and compl	ata ta	the best of my	knowledge and u	understand that m	urguent to	NMOCE	\ mulas and	
				nd/or file certain re								
public health	or the envi	ronment. The	acceptan	ce of a C-141 repo	rt by t	the NMOCD m	arked as "Final R	eport" does not	relieve the	operator	of liability	
				y investigate and re								
	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
state,	51 10 Dai 14						OIL CON	SERVATIO	N DIVI	SION		
	4	1	,	1			<u> </u>	<u> </u>	1, 21, 1,	<u> </u>		
Signature: Leverly 4- Conf												
						Approved by District Supervisor:						
						of 1 D 11 For Charlie						
Printed Name: Beverly J. Cox						Prandon	Dowell "	Percin			1	
Title: Sr. Environmental Technologist						Approval Date: 1-4-8 Expiration Date:						
Title:	Sī.	LITYII OIIINE	iilai ie	ciniologist		Approvar Dai		Expirati	on Date.			
E-mail Addre	ss: bever	ly.j.cox@c	aosono	hillips.com		Conditions of	f Approval:				1	
]	• •		Attac	hed 🔲	[
							•					
Date: 1/2	/08 Phon	e: 505-324	-6194									