

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 22878

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Energen Resources, Inc.	Contact Kellie Skelton	
Address 2198 Bloomfield Hwy.	Telephone No. 505-566-4682	
Facility Name Jicarilla 89 #6	Facility Type On Shore Well site	
Surface Owner Jicarilla	Mineral Owner: Federal	Lease No. Jicarilla 89 #6


LOCATION OF RELEASE

Unit Letter D	Section 13	Township 27N	Range 3W	Feet from the 990	North/South Line North	Feet from the 990	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	-------------	----------------------	---------------------------	----------------------	------------------------	----------------------

Latitude 36.57791

Longitude -107.10117

NATURE OF RELEASE

Type of Release Spill from tank	Volume of Release 144 bbls	Volume Recovered 33 bbls
Source of Release: Condensate tank	Date and Hour of Occurrence Sometime on 03/10/2005	Date and Hour of Discovery 1015 am 03/11/2005
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Oil Conservation Division, Monica Kuehling	
By Whom? Ernest Cardona	Date and Hour 03/11/2005 10:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Valve had frozen and cracked. When valve warmed the fluid was able to leak in to secondary containment		
Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> Clean up action is still in progress. The pit tank and separator have been moved to another area on location so that the soil beneath the equipment can be removed. The soil clearance limits will meet the most stringent of the requirements being the Jicarilla at 100 ppm. Once the soil is removed, samples will be collected and sent to a laboratory for analysis. Upon verification that the samples are confirmed to be below the 100 ppm, the soil will be replaced with soil that has been approved by Jicarilla Tribal personnel.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kellie J. Skelton	Approved by District Supervisor:  for Charlie Perrin	
Title: Environmental & Safety Coordinator	Approval Date: 3/31/05	Expiration Date:
E-mail Address: kskelton@energen.com	Conditions of Approval: Submit record of cleanup on Final Report C-741	Attached <input type="checkbox"/>
Date: March 25, 2005	Phone: 505-566-4682	

* Attach Additional Sheets If Necessary

NDG-F0509041630