District I + 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia. NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

20 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised March 17, 1999 Submit 2 Copies to appropriate

Form C-141

District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action 50 039 25581 **OPERATOR** X Initial Report Final Report Name of Company Williams Production LLC Contact Michael K. Lane Address 999 Goddard Ave, Ignacio, CO Telephone No. **970-563-3319** Facility Name Rosa Unit 165 Facility Type Gas Well Mineral Owner BLM Lease No. SF-078766 Surface Owner BLM LOCATION OF RELEASE North/South Line Feet from the East/West Line Feet from the County Unit Letter Section Township Range 1655' 31 N 6 W Ν 1850' W Rio Arriba F 25 NATURE OF RELEASE Type of Release BGT cracked. Volume of Release N/A Volume Recovered N/A Source of Release Freezing water cracked fiberglass tank. Date and Hour of Occurrence Date and Hour of Discovery Prior to 1/14/05 1/14/05 12:00 MST [If YES, To Whom? Was Immediate Notice Given? Denny Foust of NMOCD @ 1/14/05 16:00 MST X Yes No Not Required Date and Hour 🗆 By Whom? Michael K. Lane T Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes X No If a Watercourse was Impacted, Describe Fully * escribe Cause of Problem and Remedial Action Taken.* BGT failure discovered during sump inspection. Fiberglass tank cracked probably due to frozen water in tank. Remedial actions included; tank pumped of liquids and tank removed for replacement. Outer plastic liner in tack and no holes or tears found. Some stained soil around liner during tank removal suspected from incidental spills in secondary containment surrounding BGT. BGT removed from service, and replaced with an subgrade tank. Describe Area Affected and Cleanup Action Taken.* Former tank excavation prepared and new subgrade tank installed to replace BGT. Soil sample collected to assess possibility of impact. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Michael K. Lane, PE

Approval Date:

Phone: (505) 632-4625

Title: Environmental Specialist

Date: 1/31/05

Conditions of Approval: in well file:

Expiration Date:

Attached |