

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 25124

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP America	Contact Donald Brooks
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name Bolack B 8	Facility Type Gas Well

Surface Owner: Federal	Mineral Owner	Lease No. NM 012202
------------------------	---------------	---------------------

LOCATION OF RELEASE

Unit Letter C	Section 33	Township 28N	Range 08W	Feet from the 1020	North/South Line North	Feet from the 1690	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: 4% KCL Water Condensate D.B.	Volume of Release: 6 barrels	Volume Recovered: 0 barrels
Source of Release; Thief hatch of tank	Date and Hour of Occurrence 3/23/05 8:30 PM	Date and Hour of Discovery 3/23/05 8:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Triple S called in leaking condensate on the Bolack B 8. A BP tech was dispatched and discovered a leaking dump line going to the condensate tank. The well was shut in, and a work order will be entered to repair the leak. 6 barrels of condensate released, none recovered.

Describe Area Affected and Cleanup Action Taken.*

The spill immediately soaked into the soil and raked over. One call has been initiated. The surrounding soil will be excavated and taken to the BP Landfarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Donald Brooks	Approved by District Supervisor:  for Charlie Perrin	
Title: Field Environmental Coordinator	Approval Date: 4/18/05	Expiration Date:
E-mail Address: brooksd2@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/8/05	Phone: 326-9425	

* Attach Additional Sheets If Necessary

n DGF 0570829526