

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 25140

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Williams Production	Contact	Michael K. Lane <input type="checkbox"/>
Address	999 Goddard Ave, Ignacio, CO 81137	Telephone No.	970/563-3319 <input type="checkbox"/>
Facility Name	Rosa 88	Facility Type	Well Site <input type="checkbox"/>

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	SF-078767 <input type="checkbox"/>
---------------	-----	---------------	-----	-----------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	08	31 N	06W					Rio Arriba <input type="checkbox"/>

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Produced Water	Volume of Release	~60bbl	Volume Recovered	None
Source of Release	Produced Water Tank	Date and Hour of Occurrence	Prior 2/26/05 11:00 AM	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust, NMOCD		
By Whom?	Michael Lane	Date and Hour	2/26/05 12:45PM	29 30 31	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.
Heavy rain and snow during week and extremely poor road conditions prevented water trucks from making necessary water removal. Upon discovery well shutin, water trucks again notified of need to make haul and recovery any water spilled. Impacted soils to be remediated once weather/site conditions improve.

Describe Area Affected and Cleanup Action Taken. Overfill liquids mainly contained within secondary containment berms. Approx. 1bbl of water with slight oil skim on water flowed outside of berm containment damaged by weather. Berm repaired by hand until roustabout crew could be mobilized to make permanent repairs.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor  for Charlie Perrin, Acty	
Title: FCA Environmental Specialist	Approval Date: 3/21/05	Expiration Date:
E-mail Address: Myke.Lane@Williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/22/05	Phone: (505) 330-3198	

* Attach Additional Sheets If Necessary

NDGF 0508031609