<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resource

> Oil Conservation Division 1220 South St. Francis Di Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

				(	OPE	ERATOR	War Startie	Ш.,	Initial Rep	ort X Final Report	
Name of Company ConocoPhillips Company						Contact Juanita Farrell					
Address 5525 Hwy. 64, Farmington, NM 87401						Telephone No					
Facility Name FC FEDERAL 1					Facility Type Producing			as Well	API # 30-045-27544		
Surface Owner Federal Mineral Owner				vner	Federal SF-0765			554			
LOCATION OF RELEASE											
Unit Letter	r Section Township Rang		Range	ge Feet from the N		th/South Line	Feet from the	East/	West Line	County	
G	30	T32N	10W	1545'	N	lorth	1345"	East		San Juan	
Latitude 36.95954° Longitude 107.91945°											
NATURE OF RELEASE											
Type of Relea	ise – Prod	uced wate	r		Volume of Rel	olume of Release – <b>5 BBL</b> Volume Recovered - <b>5 BBL</b>					
Source of Release. Production water storage tank						Date and Hour of Occurrence Dat				Date and Hour of Discovery	
overflowed.						before 2/03/05 2/03/05			2/03/05 a	pprox. 8:00am	
Was Immediate Notice Given?						If YES, To Whom?					
☐ Yes ☐ No ☐ Not Required						Denny Foust – OCD – 02/04/05 via email					
						Mark Kelly – BLM – 02/04/05 via email					
By Whom <sup>9</sup> Juanita Farrell						Date and Hour – 2/04/05 – 11:00 am via e-mail					
Was a Waterc	ourse Reac			If YES, Volume Impacting the Watercourse.							
Yes No											
If a Watercourse was Impacted, Describe Fully *											
Describe Cause of Problem and Remedial Action Taken * A produced water spill of approximately 5 bbl was discovered on 2/03/05. The spill resulted when a 500 bbl tank ran over. The spill was contained within the bermed area. A vacuum truck recovered approximately 5 bbl of fluid containing compressor lube oil and produced water.											
Describe Area Affected and Cleanup Action Taken.* No water left the berm. A vacuum truck recovered approximately 5 bbl of fluid. A soil sample was taken. The contaminated soil will be excavated and hauled to Envirotech landfarm, if necessary. Unless the investigation and remediation shows further soil impact this will be the final report.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: Quont Fairell						OIL CONSERVATION DIVISION					
Printed Name Juanita Farrell						Approved by District Supervisor: For Charlie Pervisor					
Title: Regulatory Analyst						Approval Date: 2/16/05 Expiration Date:					
	<del>_</del> <del>_</del>			phillips.com		Conditions of	17				
Date: 2/04/05 Phone: 505-599-3419										Attached	

\* Attach Additional Sheets If Necessary

n DGF 050 475 1064