

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-25430 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company Williams Production	Contact Michael K. Lane
Address PO Box 640	Telephone No. 505-634-4219
Facility Name Rosa 8A	Facility Type Well Site

Surface Owner BLM	Mineral Owner BLM	Lease No. 123456789
--------------------------	--------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter D	Section 26	Township 31 N	Range 06W	Feet from the 963	North/South Line FNL	Feet from the 1184	East/West Line FWL	County San Juan
-------------------------	----------------------	-------------------------	---------------------	-----------------------------	--------------------------------	------------------------------	------------------------------	---------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~5 bbl	Volume Recovered ~4 bbl
Source of Release Overfilled produced water drain tank (SGT).	Date and Hour of Occurrence <2/19/06 9:30 AM	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.



Describe Cause of Problem and Remedial Action Taken.

Water hauling contractor failed to drain produced water storage tank. Tank overfill filled SGT drain tank and over ran SGT slightly before production tech checked wellsite and discovered problem. All produced water contained in secondary containment. Vac trucks immediately deployed to site to recover spilled water and drain production tank.

Describe Area Affected and Cleanup Action Taken.

No water recovered, soaked into well pad soils. As well pad to be sterilized during production life of well, will reclaim well site when well P&A'd. No further action being taken at this time. Making arrangements to install a remote level sensor and alarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor: 	
Title: SJB EH&S Specialist	Approval Date: 2/24/06	Expiration Date:
E-mail Address: myke.lane@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/20/06 Phone: (505) 330-3198		

* Attach Additional Sheets If Necessary

N NGF0605554027