

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RCVD DEC 21 06
OIL CONS. DIV.
DIST. 3
Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP America	Contact Kevin Hansford
Address 200 Energy Court	Telephone No. (505) 326-9279
Facility Name A. L. Elliot B #001A	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No NMSF078132
---------------------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter F	Section 10	Township 29N	Range 09W	Feet from the 1160	North Line	Feet from the 800	West Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------	-----------------------------	-----------	---------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release: Condensate	Volume of Release 84 Barrels	Volume Recovered 0
Source of Release: Tank load line	Date and Hour of Occurrence: 12/12/06 8:00am	Date and Hour of Discovery 12/12/06 11:45 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin	
By Whom? Kevin Hansford	Date and Hour: 12/12/2006 1:15 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The valve on the 300bbl tank was found open with the seal broken and the valve at the end of the load line was broken off at the threads. Oil had run outside of the berm and off of location. Vandalism/Theft is the likely cause.

Describe Area Affected and Cleanup Action Taken.* The well was shut it and the agency notifications were made. Cleanup operations started on 12/14 after BLM inspection and approval to clean up offsite impacted soil. The soil will be excavated and transported to the Crouch Mesa Landfarm. Clean soil will be brought in to backfill the excavation. A final report with pictures will be submitted after cleanup operations are completed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kevin Hansford		Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator		Approval Date: 12-21-06	Expiration Date:
E-mail Address: hanske@bp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/19/06 Phone: 505-326-9279			

* Attach Additional Sheets If Necessary

~BP0701741760