


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District/Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	HUERFANO UNIT	284	Facility Type Gas Well
Surface Owner	Federal	Mineral Owner	Federal
Lease No.		NMNM-03016	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	11	025N	009W	850	South	1590	East	San Juan

NATURE OF RELEASE

Type of Release	No Release - Fire	Volume of Release	0 BBLS	Volume Recovered	0 BBLS
Source of Release	No Release - Fiberglass Pit Tank Fire	Date and Hour of Occurrence	1/24/2006	Date and Hour of Discovery	1/24/2006
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Ed Hasely	Date and Hour	1/25/2006 10:00:00 A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully *

NA

Describe Cause of Problem and Remedial Action Taken *

It was discovered that the fiberglass pit tank had caught fire. The fire was out when it was discovered. The location had been visited on 1/19/06 so the fire occurred sometime after that.

Describe Area Affected and Cleanup Action Taken.*

The pit tank was destroyed. There also was damage to the piping leading to the pit tank and some of the plastic gauge covers on the separator were melted. The cause of the fire is unknown with either static electricity or the burner on the separator being the probably source of ignition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Ed Hasely	Approved by District Supervisor:	 for Charlie Perry
Title: Environmental Representative	Approval Date:	1/27/06	Expiration Date:
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:	Attached	
Date: 1/25/06	Phone: (505) 326-9841 or 9537	<input type="checkbox"/>	

* Attach Additional Sheets If Necessary

N D G F 060 2734941