


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30 045 32126

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Production	Contact Michael K. Lane
Address PO Box 640	Telephone No. 505-634-4219
Facility Name Cox Canyon 200A	Facility Type Well Site

Surface Owner BLM	Mineral Owner BLM	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter O	Section 9	Township 32 N	Range 11W	Feet from the 1050	North/South Line FSL	Feet from the 2305	East/West Line FEL	County San Juan
-------------------------	---------------------	-------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	---------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Condensate	Volume of Release ~64 bbl	Volume Recovered none
Source of Release 100 BBL Condensate Tank	Date and Hour of Occurrence Prior 9/14/06 ~12:30	Date and Hour of Discovery 9/14/06 ~12:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Steve Hayden: NMOCD & Mark Kelly: FFO-BLM	
By Whom? Myke Lane, WPX	Date and Hour 9/15/06 ~15:00 MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.		

Describe Cause of Problem and Remedial Action Taken.

Bottom of steel storage tank corroded leaving a small pin hole. Upon discovery, tank drained and separator dump shutin.

Describe Area Affected and Cleanup Action Taken.

Arrange the removal of faulty tank, excavated approximately 64CY (12X16X9) monitoring with OVM, back fill with clean soil, and replace tank with gravel base.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Michael K. Lane	Approved by District Supervisor: For: Charlie Perrin		
Title: SJB EH&S Specialist	Approval Date: 9/21/06	Expiration Date:	
E-mail Address: myke.lane@williams.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 9/20/06 Phone: (505) 330-3198			

* Attach Additional Sheets If Necessary

n BP0628339480