


District I
1625 N French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30039 25773

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name JICARILA B 13M	Facility Type PRODUCTION FACILITY

Surface Owner JICARILLA APACHE TRIBE	Mineral Owner JICARILLA APACHE TRIBE	Lease No. CONT 106
---	---	--------------------

LOCATION OF RELEASE

Unit Letter B	Section 36	Township 26N	Range 4W	Feet from the 850	North/South Line FSL	Feet from the 870	East/West Line FWL	County RIO ARRIBO
------------------	---------------	-----------------	-------------	----------------------	-------------------------	----------------------	-----------------------	-------------------

NATURE OF RELEASE

Type of Release PRODUCED OIL	Volume of Release 20-OIL BBLs	Volume Recovered 10-OIL BBLs
Source of Release PRODUCED OIL TANK	Date and Hour of Occurrence 8/12/01 HOUR-UNKNOWN	Date and Hour of Discovery 8/13/01 2:10 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

THE SEPARATOR BECAME OVERLOADED AND STARTED DUMPING WATER AND OIL TO THE OIL TANK. THIS CAUSED THE OIL TANK TO FILL UP AND SPILL INTO THE BERM AREA. ALL FREE STANDING LIQUID WAS PICKED UP WITH A VACUUM TRUCK.

Describe Area Affected and Cleanup Action Taken.*

THE SPILL OCCURRED INSIDE THE BERMED AREA. THE AREA WILL BE DUG OUT AND LANDFARMED ON LOCATION. SAMPLES WERE TAKEN TO DETERMINE DEPTH OF SOIL CONTAMINATION.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Gary Ledbetter</i>	Approved by District Supervisor: <i>Denny Zent</i>	
Printed Name: GARY LEDBETTER	for Frank Chavez	
Title: SHEAR SPECIALIST	Approval Date: 8/23/01	Expiration Date:
Date: 8/22/01 Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDG F0123555729