<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised March 17, 1999

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
30 045 23621						OPERAT] Initial	Report	Χ□	Final Report	
Name of Co Phillips Pet		ompany		Contact □ R. A. Wirtanen									
Address 5525 Hwy. 64 Farmington, NM 87401						Telephone No. □ 505-599-3462							
Facility Nar San Juan 3	ne			Facility Type□Los Pinos Ft. Pictured Cliffs South – gas well									
Surface Ow	ner		wner	Lease No. □ NMSF078998									
Bureau of l	-	agement		Manageme	ent								
LOCATION OF RELEASE													
Unit Letter Section Township Range 34 32N 7W			Feet from the 820		/South Line South	Feet from the 980	East/West Line West		Со	County □San Juan			
NATURE OF RELEASE													
Type of Rele Produced W				Volume of Release 50 bbls			Volume Recovered ☐ 45 bbls						
Source of Release						Date and H 11/19/01	lour of Occurrence				nd Hour of Discovery 11/19/01		
Dump valve on 2 mm separator "stuck open" & well unloaded Was Immediate Notice Given?						If YES, To Whom?							
X Yes No Not Required													
By Whom? □ Robert Wirtanen – Phillips Sr. Safety & Environmental Spelst						Date and Hour □ 11/20/01 1500 hrs							
Was a Watercourse Reached? Yes X No						If YES, Volume Impacting the Watercourse. N/A							
If a Watercourse was Impacted, Describe Fully.* A watercourse was not reached.													
Describe Cause of Problem and Remedial Action Taken.* A dump valve on a 2 mm separator opened automatically and emained open when the well began to unload water. The cause for the dump to													
Remain open is undetermined at this time. We have not had a history of dump valves sticking open for an extended period of time.													
Describe Are	a Affected	and Cleanup A	Action Tak	en.*									
Spilled water remained with the earthen berm of the overflowed tank and did not leave the lease. No remedia tran, and cleanup required.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
				OIL CONSERVATION DIVISION									
Signature:	Original s	igned by Rob		Deny geent									
Printed Name: Robert A. Wirtanen						Approved by District Supervisor: Cov Frank Chave >							
Title: Sr. Safety & Environmental Specialist						Approval Date: 11/26/0 Expiration Date:							
Date:	11/20/01	Pho	ne: 505-5 9	9-3462		Conditions of	/ / f Approval:			Attached			

^{*} Attach Additional Sheets If Necessary