

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141

Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

3004525473

OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	GREGG WURTZ
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	
Facility Name:	ZACHRY	Facility Type:	SWD

Surface Owner:	Fee	Mineral Owner:	Fee	Lease Number:	NMSF-080724-A
----------------	-----	----------------	-----	---------------	---------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
K	34	029N	010W	900	South	1650	West	

NATURE OF RELEASE

Type of Release:	Oil	Volume of Release:	100.2 BBLs.	Volume Recovered:	95 BBLs.
Source of Release:	Storage tank	Date and Hour of Occurrence:	12/19/2001 6:00:00 PM	Date and Hour of Discovery:	12/19/2001 12:15:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?	DENNY FOUST		
By Whom?	Gregg Wurtz	Date and Hour:	12/19/2001 2:30:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Load valve on oil storage tank froze and cracked releasing oil. Free oil was recovered and put back into storage tank. Impacted soil was landfarmed on location. Oil was very high in paraffin content (i.e., thick viscous liquid), location was in shade and ground frozen, soil type grayish green clay and most of liquid accumulated in depression for water tank. Hot water was used to float additional oil for collection by vacuum truck. Vertical extent of soil removal was limited to top 3 inches of soil.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All oil released was contained within containment berm. Area of impact limited to inside containment berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>		
Printed Name:	Gregg Wurtz		
Title: Environmental Representative	Approved by:	District Supervisor: <i>Denny Foust</i>	
Date:	Approval Date:	Expiration Date:	
Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>	