


District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



### Release Notification and Corrective Action

30 045 26617

OPERATOR

Initial Report ☐ Final Report ☒

Name of Company CONOCO INC.	Contact GARY LEDBETTER	
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837	
Facility Name MADDOX C WN FED 1E	Facility Type PRODUCTION FACILITY	
Surface Owner BLM	Mineral Owner BLM	Lease No. NM-0546

### LOCATION OF RELEASE

Unit Letter P	Section 14	Township 30N	Range 13W	Feet from the 1150	North/South Line FSL	Feet from the 1100	East/West Line FEL	County SAN JUAN
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	--------------------

### NATURE OF RELEASE

Type of Release FIRE	Volume of Release 10 MCF	Volume Recovered NONE
Source of Release ABOVE GROUND STORAGE TANK VENT	Date and Hour of Occurrence 3/10/01 NOON	Date and Hour of Discovery 3/10/01 3:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? GARY LEDBETTER	Date and Hour 3/12/01 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

DUMP VALVE ON SEPARATOR HAD STUCK OPEN AND THE VENTING GAS WAS IGNITED BY LIGHTNING CAUSING A FIRE. NO REMEDIAL ACTION WAS TAKEN

Describe Area Affected and Cleanup Action Taken.\*

THE ENARDO VALVE RUBBER SEALS WERE MELTED AND HAD TO BE REPLACED. NO CLEANUP ACTION WAS TAKEN.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor: for Frank Chavez	
Title: SHEAR SPECIALIST	Approval Date: 4/02/01	Expiration Date:
Date: 3/29/01	Phone: 505-324-5837	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDG-F010925-7537