

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045-28360

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Compressor Systems Inc.	Contact <input type="checkbox"/> Charles R. Viverette Jr.
Address P.O. Box 60760 Midland, Texas 79711-0760	Telephone No. <input type="checkbox"/> 432-495-3169
Facility Name ConocoPhillip Co.'s SJ 32-7- 219 #2 Facility	Facility Type <input type="checkbox"/> natural gas compression

Surface Owner Federal	Mineral Owner	Lease No. <input type="checkbox"/>
--------------------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	15	31N	7W	800	North	800	West	San Juan

NATURE OF RELEASE

Type of Release Screw Compressor Oil	Volume of Release ✓ 250 Gallons	Volume Recovered <input type="checkbox"/> 20 Gallons
Source of Release Screw Compressor Front Seal	Date and Hour of Occurrence Unknown	Date and Hour of Discovery <input type="checkbox"/> Nov. 7, 2005 / 12:00 P.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The front seal went out on the screw compressor. The seal or the complete compressor was replaced.

Describe Area Affected and Cleanup Action Taken.* The spill appears to be primarily on the left side of the skid, running across the location. The remedial action was to clean up as much as possible ourselves and then schedule with Foutz & Bursome for the remainder. They will remove all contaminated soil and gravel and replace it with clean soil and gravel. The contaminated soil will be taken to Envirotech's local land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Charles R. Viverette Jr.	OIL CONSERVATION DIVISION	
Printed Name: Charles R. Viverette Jr.	Approved by <input type="checkbox"/> District Supervisor: Denny Foust per BP	
Title: Environmental Specialist I	Approval Date: 11-22-05	Expiration Date:
Date: November 17, 2005	Phone: (432) 495-3169	Conditions of Approval: Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

1 DGFO532630298



ran down to here (see next picture)



