Form 3160-5 (November 1994)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVE		R	E	C			ij	1	4 2 6	Section and the second
---------	--	---	---	---	--	--	----	---	-------	------------------------

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No

	•	Familiation F	Mana Wavajo Alotted	greement, Name and/or
SUBMIT IN TRIPL	JCATE - Other instr	ructions on reverse side	1	ND MAR 3'10 L CONS. DIV.
☑ Oil Well ☐ Gas Well	Other	Revised*original sent in 9-	23-0 8. Well Name and	Nonici o
2. Name of Operator			Irene Whitney	Com#1.
Elm Ridge Exploration Co., L	LLC	`	9. API Well No.	
3a. Address	A 0 TH / / D	3b. Phone No. (include area code		·
PO Box 156. Bloomfield, NN		505-632-3476 x 201	10. Field and Pool, o	1 -
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Descript	ion)	Bisti Lower Gal	
1850 FSL X 1650 FWL			11. County or Parish	ı, Şiaie
K - Sec.21-T25N-R11W		~*	San Juan Cour	ity, NM
12. CHECK APPROPRIATE BOX	(ES) TO INDICATE NAT	TURE OF NOTICE, REPORT, OF	R OTHER DATA	į.
TYPE OF SUBMISSION	TYPE OF ACTION			· ·
Notice of Intent	Acidize	Deepen Produ	uction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat Recla	mation	Well Integrity
X Subsequent Report	Casing Repair	☐ New Construction ☐ Recor	mplete	Other
	Change Plans		orarily Abandon	1
Final Abandonment Notice	Convert to Injection	Plug Back Water	r Disposal	
determined that the site is ready for final insp	-	d only after all requirements, including re		160-4 shall be filed once ed and the operator has
Elm Ridge Exploration Co LL 9-17-09 Plug #1.TBG at 5479 retainer at 5740' pump 17 sk 9-18-09 Plug #2: Retainer se retainer, 17 sks above.9-18-01715' set retainer at 1707' puset retainer at 1360' pump 24 at 608' cirulate hole clean w/bradenhead.9-22-09 Tag cer Farm. 9-22-09 Move service All work was witnessed by Jo	C, has plugged and a 9 no CIBP at 5300' tags of cement mixed with at 4931' circulate house plug #3. TBG at 219 mp 61 sks of cement 43 sks of cement, disp 35 bbls FW, pump 185 ment 40' from the surfunit off location. Note the Ruybalid w/ the BLM	bandoned the above well as g bridge at 5800' unable to v th 15.6 PPG 1.18 yield,displa le clean w/ 115 bbls FW,pur 93' spot 26 sks of cement.9- w/ 9 sks above retainer, 9-1 blaced w/ 61 sks above retain 5 sks of cement down 5 1/2" face.Rig down service unit,c All cement used was class	s follows; vork through bridge. aced w/ 31 bbls FW. mp 44 sks of cement 19-09 Plug #4; Perf 4 19-09 Plug #5; Perf 4 ner 9-19-09 Plug #6 casing, circulate 5 b lean pits and send to	Set 5 1/2"  1,27 sks below 4 holes at holes at 1417 6 Perf 4 holes bibls out of Envirotech Earth
Elm Ridge Exploration Co LL 9-17-09 Plug #1.TBG at 5479 retainer at 5740' pump 17 sk 9-18-09 Plug #2: Retainer se retainer, 17 sks above.9-18-(1715' set retainer at 1707' puset retainer at 1360' pump 24 at 608' cirulate hole clean w/bradenhead.9-22-09 Tag cer Farm. 9-22-09 Move service All work was witnessed by Journal of the properties of the properti	C, has plugged and a 9 no CIBP at 5300' tags of cement mixed with at 4931' circulate ho 09 Plug #3:TBG at 219 ump 61 sks of cement 43 sks of cement, disp 35 bbls FW, pump 185 ment 40 ' from the surfunit off location. Note the Ruybalid w/ the BLM is true and correct	bandoned the above well as g bridge at 5800' unable to vit 15.6 PPG 1.18 yield displayed le clean w/ 115 bbls FW.pur 93' spot 26 sks of cement 9-1 w/ 9 sks above retainer. 9-1 blaced w/ 61 sks above retained 5 sks of cement down 5 1/2" face. Rig down service unit, coment used was classed.	s follows; vork through bridge. aced w/ 31 bbls FW. mp 44 sks of cement 19-09 Plug #4; Perf 4 19-09 Plug #5; Perf 4 ner 9-19-09 Plug #6 casing, circulate 5 blean pits and send to G mixed at 15.6 PPC	Set 5 1/2"  1,27 sks below 4 holes at holes at 1417 6 Perf 4 holes bibls out of Envirotech Earth
Elm Ridge Exploration Co LL 9-17-09 Plug #1.TBG at 5479 retainer at 5740' pump 17 sk 9-18-09 Plug #2: Retainer se retainer, 17 sks above.9-18-01715' set retainer at 1707' puset retainer at 1360' pump 24 at 608' cirulate hole clean w/bradenhead.9-22-09 Tag cer Farm. 9-22-09 Move service All work was witnessed by Journal of the service at 14 the foregoing	C, has plugged and a 9 no CIBP at 5300' tags of cement mixed with at 4931' circulate ho 09 Plug #3:TBG at 219 ump 61 sks of cement 43 sks of cement, disp 35 bbls FW, pump 185 ment 40 ' from the surfunit off location. Note the Ruybalid w/ the BLM is true and correct	bandoned the above well as g bridge at 5800' unable to with 15.6 PPG 1.18 yield, displayed clean w/ 115 bbls FW, pur 93' spot 26 sks of cement. 9-1 blaced w/ 61 sks above retains 5 sks of cement down 5 1/2" face. Rig down service unit, c All cement used was class of the product of the produ	s follows; vork through bridge. aced w/ 31 bbls FW. mp 44 sks of cement 19-09 Plug #4; Perf 4 19-09 Plug #5; Perf 4 ner 9-19-09 Plug #6 casing, circulate 5 b lean pits and send to	Set 5 1/2"  1,27 sks below 4 holes at holes at 1417 6 Perf 4 holes bibls out of Envirotech Earth
Elm Ridge Exploration Co LL 9-17-09 Plug #1.TBG at 5479 retainer at 5740' pump 17 sk 9-18-09 Plug #2: Retainer se retainer, 17 sks above.9-18-(1715' set retainer at 1707' puset retainer at 1360' pump 24 at 608' cirulate hole clean w/bradenhead.9-22-09 Tag cer Farm. 9-22-09 Move service All work was witnessed by Journal of the properties of the properti	C, has plugged and a 9 no CIBP at 5300' tags of cement mixed with at 4931' circulate ho 09 Plug #3:TBG at 219 ump 61 sks of cement 43 sks of cement, disp 35 bbls FW, pump 185 ment 40 ' from the surfunit off location. Note the Ruybalid w/ the BLM is true and correct	bandoned the above well as g bridge at 5800' unable to vit 15.6 PPG 1.18 yield displayed le clean w/ 115 bbls FW.pur 93' spot 26 sks of cement 9-1 w/ 9 sks above retainer. 9-1 blaced w/ 61 sks above retainer 5 sks of cement down 5 1/2" face. Rig down service unit, coment used was class of the cement used	s follows; vork through bridge. aced w/ 31 bbls FW. mp 44 sks of cement 19-09 Plug #4; Perf 4 19-09 Plug #5; Perf 4 ner 9-19-09 Plug #6 casing, circulate 5 blean pits and send to G mixed at 15.6 PPC	Set 5 1/2"  1,27 sks below 4 holes at holes at 1417' 6 Perf 4 holes bibls out of Envirotech Earth
Elm Ridge Exploration Co LL 9-17-09 Plug #1.TBG at 5479 retainer at 5740' pump 17 sk 9-18-09 Plug #2: Retainer se retainer, 17 sks above.9-18-(1715' set retainer at 1707' puset retainer at 1360' pump 24 at 608' cirulate hole clean w/bradenhead.9-22-09 Tag cer Farm. 9-22-09 Move service All work was witnessed by Journal of the properties of the properti	C, has plugged and a 9 no CIBP at 5300' tags of cement mixed with at 4931' circulate howard at 4931' circulate howard at 4931' circulate howard at 4931' TBG at 219 mp 61 sks of cement, disposed at 55 bbls FW, pump 185 ment 40 ' from the surfunit off location. Note the Ruybalid w/ the BLM is true and correct.	bandoned the above well as g bridge at 5800' unable to vit 15.6 PPG 1.18 yield displayed le clean w/ 115 bbls FW.pur 93' spot 26 sks of cement 9-1 w/ 9 sks above retainer. 9-1 blaced w/ 61 sks above retainer 5 sks of cement down 5 1/2" face. Rig down service unit, coment used was class of the cement used	s follows; vork through bridge. aced w/ 31 bbls FW. mp 44 sks of cement 19-09 Plug #4;Perf 4 19-09 Plug #5;Perf 4 ner 9-19-09 Plug #6 casing, circulate 5 belean pits and send to G mixed at 15.6 PPC	Set 5 1/2"  1,27 sks below 4 holes at holes at 1417' 6 Perf 4 holes bibls out of Envirotech Earth

(Instructions on reverse)

NMOCD

MOV 1 6 2009