Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires March 31, 2007

5 Lease Senal No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

	SF-078384
6	If Indian, Allottee or Tribe Name

abandoned we	ell. Use Form 3160 - 3 (2	APD)=for_such_pro	posals.				
SUBMIT IN TR	7 If Unit or CA/Agreement, Name and/or No						
1 Type of Well Oil Well OI Gas Well Other MAR I 5 2010					8 Well Name and No.		
2 Name of Operator HEP Oil GP, 3a Address	LLC Ev	TORU Of Land Management Familian Flaid Office 3b Phone No (include area code) 940 665-4373		Newsom B #19 9. API Well No. 30-045-23919 10 Field and Pool, or Exploratory Area			
201 W. California Street, Gain	esville, Texas 76240						
4 Location of Well (Footage, Sec., Section 8 T26N & R8W, 790 F	Ballard Pictured Cliffs (Gas) 11 County or Parish, State San Juan County, New Mexico EPORT, OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily Ab		Water Shut-Off Well Integrity Other		
	ed Operation (clearly state all perti- ectionally or recomplete horizontall		-	• • •	and approximate duration thereof. of all pertinent markers and zones		

CZ

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

With an approximate start date of late April 2010 (weather permitting) and a duration of 5 days:

- 1) Rig Up Service Rig.
- 2) Move in work string.
- 3) Isolate casing leak with packer and retrievable bridge plug.
- 4) Squeeze off leak.
- 5) Drill out.
- 6) Acidize Pictured Cliffs with 1100 gals 15% NEFE acid.
- 7) Swab and return well to production.

Notify NMOCD 24 hrs prior to beginning operations

RCVD MAR 18'10

OIL CONS. DIV. DIST. 3

MAR 1 6 2010

Date

SQUEEZE MUST BE PRESSURE TESTED TO A MINIMUM OF 500 PS1

IN ACCORDANCE WITH NMOCD RULE 19.15.25.14

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Anthony S. Cutia

Title Operations Manager

Date 03/10/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE
Original Signed: Stephen Mason

Approved by

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction