Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVED				
	OMB No	1004-0137			
	Expires: Ju	ily 31, 2010			
ease Serial No.					


J. Lease Serial No. NMSF 078882


SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for the proposals in the control of the con		6. If Indian, Allottee or Tribe Name			
	T IN TRIPLICATE – Other			7. If Unit of CA/Agre	eement, Name and/or No.
1. Type of Well	03.07		E 2010	Canyon Largo Unit	
	Oil Well Gas Well Other		8. Well Name and No. Canyon Largo Unit #356		
2. Name of Operator Huntingotn Energy, L.L.C. Farmington Field Office 9. API Well No. Bureau of Land Management 30-039-23863					
3a. Address 908 N.W. 71st St. Oklahoma City, OK 73116	3b. Phone No. (include area code) 405-840-9876		10. Field and Pool or Exploratory Area Devils Fork Gallup		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SESS 910' FSL & 860' FEL Sec 20, T25N-R6W			11. Country or Parish, State Rio Arriba Co., NM		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NA	ATURE OF NOTIC	E, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	_	uction (Start/Resume)	Water Shut-Off
Cukas ayant Dancet	Alter Casing Casing Repair	Fracture Treat New Construction	=	mation mplete	Well Integrity Other
Subsequent Report	Change Plans	Plug and Abando	on Temp	orarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Wate	r Disposal	
testing has been completed. Final a determined that the site is ready for	ork will be performed or project operations. If the operation Abandonment Notices must be final inspection.)	vide the Bond No. on file on results in a multiple con be filed only after all requi	with BLM/BIA. R npletion or recompl rements, including	equired subsequent re letion in a new interval reclamation, have beer	ports must be filed within 30 days l, a Form 3160-4 must be filed once
Huntington Energy, L.L.C. plans to plug and abandon the above referenced well. The following is the procedure:					RCVD JUL 20'10
 MICU. Bleed well down. ND WH. NU BOP. COOH w/tubing. RU Basin WL & set CIBP @ 5650'. Dump bail 35' cement on top of plug. 			OIL CONS. DIV.		
 MV Plug at 3900'- 3800' w/10 sx cmt. Picture Cliffs and Fruitland combination plug from 2350' – 1950' w/30 sx cmt. Kirtland and Ojo Alamo combination plug from 1850' - 1600' w/30 sx cmt. 				DIST. 3	
Casing Plug: circulate cem bradenhead. Install dry ho	ent from 396' back to surfa	ace – 50 sx. ND BOP, fil	I casing to top. I	Place top wellhead fl	ange with plug, close casing and
Nacimiento	Pl-z 665'-566	- invide your	sile the	4 / tesing	
14. I hereby certify that the foregoing is tr Catherine Smit	ue and correct. Name (Printed	/Typed) Title Re	gulaton		
Signature Catheline Smit	1	Date 07/			,

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Original Signed: Stephen Mason Date [U] 1 6 2010 Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 356 Canyon Largo Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Mesaverde plug from 3900' 3800'*.
- b) Place a cement plug from 3190' 3090' to cover the Chacra top.
- c) Place the Nacimiento plug from 665' 565' inside and outside the 4 1/2" casing.
- d) Place the Surface plug from 268' to surface inside and outside the 4 1/2" casing.

*You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.