## RECEIVED

Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCT 01 2010

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT	
Farming	ton Field OfficeLease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLES u of L	and ManagerNMSF 078768
Do not use this form for proposals to drill or to re-enter a	6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for such proposa	ls.
SUBMIT IN TRIPLICATE – Other instructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.
. 0	Rosa Unit
1. Type of Well	
Oil Well Gas Well Other SWD	
	8. Well Name and No.
	Rosa Unit SWD #2
2. Name of Operator	9. API Well No.
Williams Production Company, LLC  3a. Address  3b. Phone No. (include area code)	30-039-30812
PO Box 640 Aztec, NM 87410 505-634-4208	10. Field and Pool or Exploratory Area Entrada
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	11. Country or Parish, State
2460' FNL & 2095' FWL, sec 25, T31N, R5W	Rio Arriba
5 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE O	DE NOTICE, REPORT OR OTHER DATA
	F ACTION
Notice of Intent  Acidize  Deepen	Production (Start/Resume) Water Shut-Off
	Reclamation Well Integrity
Subsequent Report Casing Repair New Construction	Recomplete Other
Subsequent Report	Temporarily Abandon FINAL CASING
Final Abandonment Convert to Injection Plug Back	Water Disposal
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate	
duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all	
requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)	
<u>9/10/10- THRU 9/24/10- DRILL 8 ¾" HOLE</u>	ACCEPTED FOR RECORD
0/05/40 TD 0.3/# DDOD HOLE @ 0000/ 4000 HD0	007 3 5 0040
9/25/10- TD 8 3/" PROD HOLE @ 9383", 1600 HRS	OCT 2 5 2010
9/26/10- CIRC & COND HOLE	FARMINGTON FIELD OFFICE BY TI SOLVESS
	RCVD OCT 28'10
14. I hereby certify that the foregoing is true and correct.	OIL CONS. DIV.
Name (Printed/Typed)	nici o
Larry Higgins Title Permit Su	pervisor Examination
Signature Magn Date 10-01-1	0
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by	
Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements of representations as to any matter within its jurisdiction.	

## Rosa Unit SWD #2 - Page 2

9/27/10- RAN 7", 232 JT'S, 29#, L-80, LT&C, 8rd, CSG SET @ 9380', FC @ 9334', MARKER JT @ 5600',
SPOT IN HOWCO & RIG UP CMT LINES. TEST LINES & START CMT JOB // COMPUTER ON PUMP TRUCK WENT DN // SHUT DN &
SHUT VALVE TO FOAMER ADDITIVE // RE BOOT COMPUTER // START PUMPING AGAIN BUT FORGOT TO OPEN VALVE TO ADDITIVE.
CMT JOB NO GOOD. RIG UP TO DISPLACE CMT W/ RIG PUMP DISPLACE CMT W/ RIG PUMP @ 4 BBL'S/MIN // LOCKED UP @ 260
BBL'S +/- INTO DISPLACEMENT // NO MOVEMENT IN PIPE. HOOK HALLIBURTON BACK UP & TRY TO GET FLUID MOVING AGAIN &
TRY TO WORK PIPE FREE, NO LUCK

9/28/10- PICK UP 1 JT DP & TEST HYDRIL AGAINST 7" CSG @ 1500 PSI FOR 30 MIN. AFTER REPAIR LEAKS, GOT GOOD TEST // TEST PUMP & CHART RECORDER USED. PICK UP 4 x 4.5" DC & 3.5" DP OFF RACKS & TIH W/ 6-1/8" BIT (BIT #9) NOTICE TO BLM OF BAD CMT ON 7" & INTENT TO SET SLIPS, CUT OFF, RE-TEST HYDRIL, & CLEAN OUT CMT @ 4:00 PM 9/28/2010 - MESSAGE TO NOTIFICATION LINE, NOTICE TO NMOCD OF BAD CMT JOB ON 7" CSG & INTENT TO SET SLIPS, CUT OFF, & RE- TEST HYDRIL & CLEAN OUT CMT- SPOKE TO STEVE HAYDEN @ 3:45 PM 9/28/2010. ✓

9/29/10- CIRC & COND MUD

9/30/10- DRLG CMT F/8770' T/9300' /// DRLG GOT HARD & TORQUE UP @ 9300' CIRC. & COND. MUD /// WAIT ON ORDERS. DECISION MADE TO MOVE IN COMPLETION RIG AND SQUEEZE. RECEIVED AUTHORIZATION TO PROCEED FROM JIM LOVATO, FFO. ✓

NOTE- CASING TEST & SQUEEZE INFORMATION INCLUDING TOC WILL BE REPORTED ON COMPLETION PAPER WORK ✓ DRILLING RIG RELEASED ON 10/1/10 @ 0600 HRS ✓