Submitted in lieu of Form 3160-5 (June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT" - for such proposals.

RECEIVED

FORM APPROVED

Budget Bureau No. 1004-0135

AUG 25 2010

Expires: March 31, 1993

Farmington Field Office Bureau of Land Management

1. Type of Well: Gas		5. Lease Number: SF-079394	
2. Name of Operator: BURLINGTON RESOURCES OIL &	GAS COMPANY LP	6. If Indian, allottee or Tribe Name:	
3. Address and Phone No. of Operator: P. O. Box 4289, Farmington, NM 874 (505) 326-9700		7. Unit Agreement Name: NMNM-78 409C-PC 8. Well Name and Number: SAN JUAN 27-5 UNIT 154R	
4. Location of Well, Footage, Sec. T, R, U: FOOTAGE: 1650' FSL & 1035' FEL S: 21 T: 027N R: 005W		9. API Well No. 3003927277 10. Field and Pool: PC - TAPACITO::PICTURED CLIFFS 11. County and State:	
	MATERIA SE	RIO ARRIBA, NM	***
12. CHECK APPROPRIATE BOX TO INDICATE Notice of Intent Subsequent Report Final Abandonment Abandonment	Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut Off	
	and produced natural gas and ent	Convérsion to Injection rained hydrocarbons. QUIPMENT REPAIR. RECEIVED AUG 2010	
This well was re-delivered on 8/19/2010	tions and produced natural gas and ent MORE THAN 90 DAYS DUE TO E	rained hydrocarbons.	den
This well was re-delivered on 8/19/2010 at the Notes: THIS WELL WAS SHUT IN M TP: 190 CP: 19 Meter No.: 82903 Gas Co.: WFC	tions and produced natural gas and ent MORE THAN 90 DAYS DUE TO E Initial MCF: 354	QUIPMENT REPAIR. RECEIVED AUG 2010 OIL COINS. DIV. DIST. 3	
This well was re-delivered on 8/19/2010 a Notes: THIS WELL WAS SHUT IN M TP: 190	tions and produced natural gas and ent MORE THAN 90 DAYS DUE TO E Initial MCF: 354 and correct.	QUIPMENT REPAIR. RECEIVED AUG 2010 OIL COINS. DIV. DIST. 3	-