Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

-Umender

FORM APPROVED

OMB NO.	1004-0135
Expires: Ju	ily 31, 2010

SUNDRY	NOTICES	AND	REPO	RTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
					JICARILLA APACHE			
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No						
1. Type of Well	8. Well Name and No. JICARILLA B 4M							
	☐ Oil Well Gas Well ☐ Other							
Name of Operator Contact: BRIDGET HELFRICH ENER VEST OPERATING LLC E-Mail: bhelfrich@enervest.net					9. API Well No. 30-039-29922-00-X1			
	3a. Address 3b. Phone N 1001 FANNIN STREET SUITE 800 Ph: 713-4 HOUSTON, TX 77002-6708 Fx: 713-6				10. Field and Pool, o BASIN DAKOT BLANCO MES	'A		
4. Location of Well (Footage, Se	c., T., R., M., or Survey Description	n)			11. County or Parish,	and State		
Sec 21 T26N R5W SWNE	2260FNL 2575FWL				RIO ARRIBA C	OUNTY, NM		
12. CHECK A	PPROPRIATE BOX(ES) TO	O INDICAT	E NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION			ТҮРЕ С	OF ACTION				
	Acidize	De	epen	Producti	on (Start/Resume)	Water Shut-Off		
□ Notice of Intent	Alter Casing	_	cture Treat	☐ Reclama		☐ Well Integrity		
Subsequent Report	Casing Repair	_	w Construction	☐ Recomp		⊠ Other		
Final Abandonment Notice	· · ·	_	g and Abandon	_	arily Abandon	12		
	Convert to Injection	_	_		isposal			
determined that the site is ready f	• ,	ied only after all	requirements, inclu-	ding reclamation	, have been completed,	and the operator has		
Spud thru Surf Csg reporte	d on 9/1/10.							
Cont'd thru TD:	Cont'd thru TD:				ROND	E08'10		
{***AMENDED items show	n in brackets**}				STEEL STATES	agan antara a		
10/2/10: MIRU. 10/3/10: NU BOP and test. Test csg to 1000 psi for 30 min - ok. 10/4/10: Drill cmt. Drill 8-3/4" hole f/ 426'-2014'.					OIL CONS. DIV. DIST. 3			
10/5/10: Drill f/ 2014'-3445	. Called Steve Hayden w/ N	IMOCD and E	Bryce Hammond	w/ Jicarilla Bl	_M @			
7:15am of upcoming csg jo 10/6/10: {Drill to 3453'}. Ci	rc and cond hole. TIH to was	sh and ream	LD DP, collars	&				
14. I hereby certify that the foregoin	g is true and correct	=		3'		· · · · · · · · · · · · · · · · · · ·		
	Electronic Submission #9	OPERATING	LLC, sent to the	Rio Puerco	-			
Name (Printed/Typed) BRIDGET HELFRICH			Title REGULATORY TECH.					
Signature (Electron	c Submission)		Date 12/03/2	010				
	THIS SPACE FO	R FEDERA			E			
Approved By ACCEP	TED		STEPHEN TitlePETROLE		ER	Date 12/06/20		
onditions of approval, if any, are attacertify that the applicant holds legal or hich would entitle the applicant to con	equitable title to those rights in the	not warrant or subject lease	Office Rio Puer					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #98532 that would not fit on the form

32. Additional remarks, continued

stabilizers. Change rams. RU csg crew. Make up shoe on shoe jt and FC and run csg. 10/7/10: RIH w/ 7" 23# N-80 LT&C csg to {3453'}. Circ hole and RU. Cmt 1st stage w/ 210sx cmt. Cmt 2nd stage w/ 430sx cmt. WOC and prep to drill w/ air hammer. Circ 55 bbls cmt to surf. 10/8/10: PU BHA, DP and TIH to DV tool. Press test csg to 1200 psi for 30 min - ok. PU 3-1/2" pipe and trip to FC. Drill FC, cmt, shoe and 7' of new hole to 3460'. TOH f/ Gyro. RU and run Gyro. TIH unloading well every 600' and blowing down. 10/9/10: Blow well and dry up. Air drill f/ 3460'-5900'. 10/10/10: Drill f/ 5900'-6000'. Blow well clean. TOH to 3480' and retrieve string floats, go back to btm. Run gyro @ 6000'. Drill f/ 6000'-6850'. Blow well clean and press test, leveled off @ 110 psi. Drill f/ 6850'-7300'. 10/11/10: Drill f/ 7300'-7489'. Blow well clean. Strap out of hole for logs. Break dwn hammer and load out. RU to log well. TIH w/ logs and went to 7414'. Log well out to 6100'. Hole bridged off and logs stuck. Trying to get log tool loose @ 6100'. 10/12-23/10: Wash and ream. Attempt to fish out stuck tools. Finally broke free. Trip out. LD fish and fish tools. 10/24/10: PU 6-1/4" bit and TIH. 10/25/10: Drill 6-1/4" bit and TIH. 10/25/10: Drill 6-1/4" both first and TIH. 10/25/10: Drill 6-1/4" both first crew. Run 4-1/2" 11.6# N-80 LT&C csg to 7629'. Circ & cond mud. 10/26/10: LD DP & DCs. RU csg crew. Run 4-1/2" 11.6# N-80 LT&C csg to 7629'. Circ & cond mud.

WO equip f/ cmt crew. 10/27/10: Pump 320sx lead cmt and tail with 50sx cmt. TOC @ 4110'. WOC. Rig released @ 06:00.

FILE IN A TIMELY MANNER