Subfait 3 Copies To Appropriate District Office a	Energy, N	State of New Medinerals and Natu		irces	Form C-103 June 19, 2008			
District I 1625 N. French Dit, Hobbs, NM 87240					WELL API N	IO.	34110 19, 200	Ϋ́
District II OII CONSERVATION DIVISION					30-045-20945			
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.				5. Indicate T	ype of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505				STATE	E 👿 FEE	3 🔲	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	,				6. State Oil &	& Gas Lease No		
87505					E-3148-7	0 000 2000 110		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name: Burroughs State			
1. Type of Well: Oil Well Gas Well X Other					8. Well Number			
2. Name of Operator					9. OGRID Ni	ımber		7
ENERGEN RESOURCES CORPORATION					162928			
3. Address of Operator					10. Pool name or Wildcat			
2010 Afton Place, Farmington NM 87401					Basin Fruitland Coal			
4. Well Location								İ
Unit Letter C:	840 fe	et from the No.	rth	ine and	1500 fee	et from the	West lin	ne
Section 36	To	ownship 26N	Range	1 1747	NMPM	County	Con Tuor	
Section 36		ion (Show whether		11W		County	San Juan	
	II. Elevati		<i>DN,</i> KK <i>B,</i> 99' GR	KI, GK, et	<i>c.)</i>			
						*		
12. Check A	ppropriate	Box to Indicate	Nature o	f Notice, l	Report, or O	ther Data		
NOTICE OF INTENTION TO: SUB					SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	DI LIC AND	ABANDON 🔲	DEMEDI	AL WORK	_	7 ALTEDI	ING CASING	
<u> </u>			i					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL					NG OPNS. L] PAND	Α	X
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT.					ов ′ 🗀]		
DOWNHOLE COMMINGLE					•			
DOVINITION COMMINGER								
			l		-			
OTHER:			OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.								
Energen Resources P&A'd ti	he subject	well on March 4	, 2011 ad	ccording t	o the attach	ned proceedur	e.	
				_		F		
Approved for plugging of wellbore only. Liability under bond is retained pending Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page under forms www.emnrd.state.us/ocd PNR Oll CONS DIV DIST.								D 13
DIVR		ann aistate.us/nea				242	MAR 2011	189
7 1017		٠				——————————————————————————————————————	I COME DOUBLE	7
Spud Date: 11/4/71		Dia Dalar	aa Datar		11/14/71	50	L CONS. DIV. DIS	I. 3 3/
Spud Date.		Rig Relea	ise Date.			\\^co		c\\\'
I have be sent if the table in formation	3		1	1 - 1-1-	11 - 11 - C		L CONS. DIV. DIS	****
I hereby certify that the information a	ipove is true	and complete to the	best of m	y knowleag	e and belief.		2000	
SIGNATURE	tott	TIT	LE	Regulator	y Analylst	DATE	3/10/11	
1			•	totts@ener	gen.com			
Type or print name Anna Stotts	1/	E-m	ail address		=	PHONE _	505-324-415	<u>54</u>
For State Use Only APPROVED BY	Leehl	/ ////////////////////////////////////	Deput	ty Oil & (Gas Inspec	otor, DATE A	PR 2 0 20	<u>11</u>
Conditions of Approval (if any):	C	X \						

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Energen Resources Corporation **Burroughs State #1**

March 5, 2011 Page 1 of 2

840' FNL & 1500' FWL, Section 36, T-26-N, R-11-W San Juan County, NM Lease Number: E-3148-7 API#30-045-20945

Plug and Abandonment Report

Notified NMOCD on 2/22/11

Plug and Abandonment Summary:

- 2/24/11 Start to move equipment onto location. SDFD.
- 2/25/11 Road rig and remaining equipment to location; RU. LO/TO separator and pumping unit. Open up well and Blow down 250 PSI casing pressure. Remove horse head. Unseat pumps and rods; LD polish rod. TOH and LD rods with top seat pump. ND wellhead. NU BOP and test. Unseat donut. TOH and tally 52 joints 2-3/8" tubing, perf sub and SN. Total tally 1675' KB. PU 3-7/8" mill tooth bit, bit sub with drill collars and RIH to 940'. SI well. SDFD.
- 2/28/11 Check well pressures: tubing 200 PSI and casing 85 PSI. Blow well down to pit. TIH and tag fill at 1600'. PU power swivel and establish circulation down tubing and out casing with 11 bbls of fresh water. Begin drilling at 1600' with coal fines and pipe scale in returns. Circulate clean to 1726'. Drill out CIBP at 1860'. Push BP to 2149'. Drill at 2375' with rubber and some cement in returns. Drill out to 2463' with clear water. PUH to 950'. SI well. SDFD.
- 3/1/11 Open up well; no pressures. Begin drilling at 2463'. Continue to drill through cement at 2562'. Work through stringers to 2575'. Hang back swivel. TOH and LD BHA. Round trip 4.5" casing scraper to 2572'. Wait on orders regarding CBL. SI well. SDFD.
- Open up well; no pressures. RU Basin Wireline. Perform CBL from 3241' to surface. Found TOC at 2350' and 1068'. RIH and tag existing plug #2 at 5074'. C. Perrin, NMOCD, approved tag. C. Perrin, NMOCD, approved procedure change on Plug #3.

 Plug #3 spot 14 sxs Class B cement (16.52 cf) from 2578' to 2394' to cover the Mesaverde top.

 PUH to 1500'. SI well. SDFD.
- Open up well; no pressure. TIH and tag cement at 2380'. TOH with tubing. PU 4.5" DHS cement retainer and RIH; set at 1544'. Pressure test casing to 800 PSI for 5 minutes. Plug #4 with CR at 1544' spot 20 sxs Class B cement (23.6 cf) from 1544' to 1281' to cover the Fruitland Coal perforations and Fruitland top.

 TOH with tubing. Perforate 3 squeeze holes at 765'. Establish injection rate with light blow out bradenhead. PU 4.5" DHS cement retainer and set at 714'.

 Plug #5 with CR at 714' spot 95 sxs Class B cement (112.1 cf), squeeze 80 sxs below CR and leave 15 sxs above to 517' to cover the Kirtland and Ojo Alamo tops.

 TOH and LD tubing. Perforate 3 squeeze holes at 295'. Establish circulation.

 Plug #6 mix and pump 128 sxs Class B cement (151.04 cf) down 4.5" casing from 295' to surface, circulate good cement out bradenhead. SI well and WOC. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Energen Resources Corporation Burroughs State #1

March 5, 2011 Page 2 of 2

Plug and Abandonment Summary Cont'd:

3/4/11 Open up well; no pressure. ND BOP. Found cement at surface in 4.5" casing. Issue Hot Work Permit. Cut off wellhead. Found cement down 75' in annulus.

Plug #7 mix and pump 25 sxs Class B cement (29.5 cf) to fill annulus and install P&A marker. RD. MOL.

Monica Kuehling and John Durahm, NMOCD representatives, were on location.