

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479
Facility Name: Florance No. 121 MV/DK	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 078116
------------------------	------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 24	Township T30N	Range R10W	Feet from the 960	North/South Line South	Feet from the 1105	East/West Line East	County: San Juan
------------------	---------------	------------------	---------------	----------------------	---------------------------	-----------------------	------------------------	---------------------

Latitude 36.79283 Longitude 107.83081

**NATURE OF RELEASE**

Type of Release: Condensate	Volume of Release: approx. 50 bbl	Volume Recovered: none
Source of Release: a hole near the bottom of the condensate tank	Date and Hour of Occurrence: approx. 10:00 AM, 6/20/10	Date and Hour of Discovery: 1:00 PM, 6/21/10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Buddy Shaw	Date and Hour: 6/21/10 - 2:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JUN 25 '10  
OIL CONSV. DIV.  
DIST. 3

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A small hole, likely caused by internal corrosion, was discovered near the bottom of the condensate tank. Approximately 50 bbl of condensate leaked through the hole into the bermed containment area. A small portion of the condensate seeped through the containment berm and onto the surface of the location. The well was shut in and access to the location was restricted.

Describe Area Affected and Cleanup Action Taken.\*

Soil within the bermed secondary containment area and a small area outside the berm and on the location was impacted. The impacted soil will be excavated and transported to a land farm. The tank will be removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jeffrey H. Peace</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jeffrey H. Peace		Approved by District Supervisor: <u>Brad Hill</u> For: CP	
Title: HSE Advisor		Approval Date:	Expiration Date:
E-mail Address: peace.jeffrey@bp.com		Conditions of Approval:	
Date: June 23, 2010 Phone: 326-9479		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nBP1026533061