

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

# State of New Mexico

## Energy Minerals and Natural Resources Department

### Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141  
Originated 2/13/97

Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

#### Release Notification and Corrective Action

30-039-24475

#### OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Gregg Wurtz
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	
Facility Name:	SAN JUAN 30-6 UNIT COM	467	Facility Type: Gas Well
Surface Owner:	State	Mineral Owner:	State
		Lease Number:	NMNM-013706-A

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
M	22	030N	007W	1240	South	1105	West	

#### NATURE OF RELEASE

Type of Release:	Motor Oil	Volume of Release:	10.71 BBLs.	Volume Recovered:	0 BBLs.
Source of Release:	Day barrel storage tank	Date and Hour of Occurrence:	2/1/2003 7:00:00 AM	Date and Hour of Discovery:	2/1/2003 7:00:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None impacted

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Vandalism, tank valve left open resulting in contents draining over and with in containment berm to ground. Impacted soil was removed and landfarmed on location. Approximately 3 cu yds. removed and landfarmed on location.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Soils within containment area and flow path outside of containment approximately 20 feet x 4 feet following topography. Oil stayed on location. Oil outside of berm was caused by Vertical seepage was minimized by thickness of product and frozen soil condition

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by:	<i>Benjamin Faust</i>
Title: Environmental Representative		District Supervisor:	for Frank Chavez
Date:	Phone: (505) 326-9841 or 326-9842	Approval Date:	3/19/03
		Expiration Date:	
		Conditions of Approval:	Attached: <input type="checkbox"/>

NDGF 0307829074