

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 320-2653
Facility Name	FLORANCE 2A	Facility Type	Gas Well
Surface Owner	FED	Mineral Owner	FED
Lease No.		NMSF-080244	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	030N	009W	1750	South	1500	East	San Juan

NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	136 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Storage tank	Date and Hour of Occurrence	11/9/2003 6:00:00 PM	Date and Hour of Discovery	11/10/2003 11:15:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour	11/12/2003 9:00:00 A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

None

Describe Cause of Problem and Remedial Action Taken.*

Vandalism. Operator came onto location and discovered load valve had been opened and condensate was released within and outside berm and the wells main valve had been opened and the lubercator had been removed. Approximately 136 bbls were released from the tank with approximately 30 bbls outside the berm and 10 bbls off location. Minor parafin staining was discovered 5 feet around the well head.

Describe Area Affected and Cleanup Action Taken.*

An area within and outside of the tank containment berm and off location. The area outside of the berm was limited to approximately 200 sq. ft. in the southwest corner of the location. Area off location was limited to a flow path of approximately 1 to 2 feet wide following the natural land contour approximately 200 feet from the edge of location. In addition, a minor parafin staining on the soils directly adjacent to the the well head was observed. The impacted soil was excavated. The soil is currently being landfarmed on location and returned to the excavation when suitable.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION <i>Denny Foust</i> Approved by District Supervisor: for Frank Chavez		
Printed Name: Gregg Wurtz	Approval Date: 11/19/03	Expiration Date:	
Title: Environmental Representative	Conditions of Approval:		Attached <input type="checkbox"/>
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc. com			
Date: 11/14/03 Phone: (505) 326-9841 or 9537			

* Attach Additional Sheets If Necessary

N DGF 033235-0619