

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 0 45 23772

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	BP America	Contact	Donald Brooks
Address	200 Energy Court	Telephone No.	(505) 326-9425
Facility Name	Warren LS 1A	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	
		Lease No.	SF 077123

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	13	28N	09W	1850	South	1850	East	San Juan

Latitude__ Longitude__

NATURE OF RELEASE

Type of Release	Gas Release	Volume of Release	600 MCF	Volume Recovered	0
Source of Release	Broken lubricator on plunger well.	Date and Hour of Occurrence	11/10/04	Date and Hour of Discovery	11/17/04 2:15 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Don Brooks	Date and Hour	11/18/04 8:00AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

We were notified that we had a well blowing gas, and upon response found that the plunger in the well had hit the lubricator with enough force to break the top of the lubricator. The gas release was over a number of days. Our automation showed the well was still flowing, however it was not. The automation transmitters were out of calibration, and did not allow faster detection of lubricator breach. Transmitters will be calibrated.

Describe Area Affected and Cleanup Action Taken.*

No clean up necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Donald Brooks		Approved by District Supervisor:  for Charlie Berner Act	
Title: Field Environmental Coordinator		Approval Date: 12/13/04	Expiration Date:
E-mail Address: brooksd2@bp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/30/2004 Phone: 326-9425			

* Attach Additional Sheets If Necessary

NDG-F0434848428