

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 045 29060

30-11-30 #2

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	El Paso Field Services Co.	Contact	David Bays
Address	614 Reilly Avenue Farmington, NM 87401	Telephone No.	(505) 599-2256
Facility Name	Campbell 30-1-30 #2 well connect line	Facility Type	natural gas wellhead gathering line
Surface Owner	Esther Campbell	Mineral Owner	BLM
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	30	30N	11W					San Juan

NATURE OF RELEASE

Type of Release	Heavy hydrocarbons (paraffin)	Volume of Release	20 bbl.	Volume Recovered	0
Source of Release	Pipeline corrosion leak	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	11/10/03 1:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust - Aztec OCD Office		
By Whom?	David Bays	Date and Hour	11/10/03 2:30 PM		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	15 bbl.		
If a Watercourse was Impacted, Describe Fully.*					
Paraffin was too viscous to flow, but it slowly spread down the wash adjacent to the leak point for a distance of about 50 yards.					
Describe Cause of Problem and Remedial Action Taken.*					
Release was caused by an internal corrosion leak, The line was blocked in, repaired, and returned to service.					
Describe Area Affected and Cleanup Action Taken.*					
The paraffin covered an area of about 1 yard wide by 50 yards long. All contaminated soil was excavated and shipped to a commercial landfarm.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>David Bays</i>		OIL CONSERVATION DIVISION			
Printed Name: David Bays		Approved by District Supervisor: <i>Denny Foust</i> for Frank Chavez			
Title: Principal Environmental Scientist		Approval Date: 11/18/03		Expiration Date:	
E-mail Address: david.bays@elpaso.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 11/11/03		Phone: (505) 599-2256			

\* Attach Additional Sheets If Necessary

NDGF 0332250318