


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



**Release Notification and Corrective Action**

3004525204

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>BP America</b>	Contact <b>Donald Brooks</b>
Address <b>200 Energy Court</b>	Telephone No. <b>(505) 326-9425</b>
Facility Name <b>Nye Gas Com 1A</b>	Facility Type <b>Gas Well</b>

Surface Owner: Private	Mineral Owner	Lease No. SF 076337
------------------------	---------------	---------------------

**LOCATION OF RELEASE**

Unit Letter F	Section 7	Township 29N	Range 09W	Feet from the 2225	North/South Line North	Feet from the 950	East/West Line West	County San Juan
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 10 barrels	Volume Recovered: 5 barrels
Source of Release; Dump line to production pit.	Date and Hour of Occurrence 10/18/04 9:45 AM	Date and Hour of Discovery 10/18/04 9:45 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Left phone message to Denny Foust (Reported 15 barrels)	
By Whom? Don Brooks	Date and Hour 10/18/04 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Tech arrived at location, and found the dump line from the compressor inlet scrubber to the production pit had lifted out of a collar on the pit, and sat back down on top of the cone top steel pit. The pressure of the dump lifted the line from the collar. The line had a 6" downcomer into the pit, and was changed out to a 24" downcomer. The line was also anchored to the pit with wire. The spill was originally thought to be 15 barrels, however after further investigation it was determined to be 10 barrels.

Describe Area Affected and Cleanup Action Taken.\*

The 5 barrels that was not recovered soaked into the ground in the earthen cellar around the pit..

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Donald Brooks</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Donald Brooks	Approved by District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: Field Environmental Coordinator	Approval Date: <i>11/03/04</i>	Expiration Date:
E-mail Address: brooksd2@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/18/2004 Phone: 326-9425		

\* Attach Additional Sheets If Necessary

*N.DGF0429 552394*