

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30045 32113

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Devon Energy	Contact: Steve Zink
Address: P. O. Box 6459 Navajo Dam, NM 87419	Telephone No.: 505-320-0677
Facility Name: NEBU 447A	Facility Type: Production Facility

Surface Owner: BLM	Mineral Owner: BLM	Lease No. 447A
--------------------	--------------------	----------------

LOCATION OF RELEASE

Unit Letter D	Section 36	Township 31N	Range 8W	Feet from the 1090'	North/South Line North	Feet from the 1175'	East/West Line West	County San Juan
------------------	---------------	-----------------	-------------	------------------------	---------------------------	------------------------	------------------------	--------------------

Latitude N/A Longitude N/A

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 25 Barrels	Volume Recovered: 0 Barrels
Source of Release: 1/2" Valve on water tank	Date and Hour of Occurrence: 4/27/4 @ 8 AM	Date and Hour of Discovery: 4/27/4 @ 8 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Monica Kuerling @ the OCD	
By Whom? Darren Smith	Date and Hour: 4/29/4 @ 11:15 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*: The 1/2" valve on the produced water tank pump was left open by the crew that installed the pump. Therefore when settle tank spilled over to pump tank and water reached level of inlet to pump the water went through open-ended valve. Spill was contained within the dike area.

Describe Area Affected and Cleanup Action Taken.*: 80 Sq. Ft. area in tank dikes. Fluids soaked in the ground, unable to pick up fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by District Supervisor:  for Frank Chavez	
Title: Production Foreman	Approval Date: 5/06/04	Expiration Date:
E-mail Address: Steve.Zink@dmn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/29/04 Phone: 505-320-0677		

* Attach Additional Sheets If Necessary

106F0412150592