

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 04529946

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy, Inc.	Contact: James McDaniel
Address: 382 Road 3100, Aztec, New Mexico 87410	Telephone No.: (505) 333-3701
Facility Name: Salty Dog SWD #1 (3004529946)	Facility Type: SWD

Surface Owner: Federal	Mineral Owner:	Lease No.:
------------------------	----------------	------------

LOCATION OF RELEASE

Unit Letter B	Section I	Township 29N	Range 15W	Feet from the 1200	North/South Line FNL	Feet from the 1380	East/West Line FEL	County San Juan
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	--------------------

Latitude: 36.760095 Longitude: -108.364370

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 80 Bbls	Volume Recovered: 80 Bbls
Source of Release: Tank Failure	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 3/21/10 at 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Ms. Kim Champlin	Date and Hour March 22, 2010, 14:11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken.*



The bottom of a steel storage tank at the Salty Dog SWD #1 failed, releasing its contents into a lined berm. The 80 bbls was confined to the lined berm and was removed by World Star Development. The tank was repaired and put back into service.

Describe Area Affected and Cleanup Action Taken.*

All 80 bbls of water was recovered from inside the lined tank berm. No soil was affected and no cleanup activities were taken.

RCVD APR 6 '10
OIL CONS. DIV.
DIST. 3

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: James McDaniel	Approved by District Supervisor: 	
Title: EH&S Specialist	Approval Date: 4/9/10	Expiration Date:
E-mail Address: James_McDaniel@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/1/2010	Phone: 505-333-3701	

NRMD 1010235437