Submit 3 Copies To Appropriate District Office	State of New Me			Form C-103
District I	Energy, Minerals and Natural Resources		<u> </u>	Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II			VELL API NO. 0-045-31946	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		Indicate Type o	f Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE [FEE 🛛
istrict IV Santa Fe, NM 8/505		505	. State Oil & Gas	Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Sha Shar Cam	
PROPOSALS.)		- 67A L	Sly Slav Com 8. Well Number	
1. Type of Well:	MAR 2000		8. Well Number	
Oil Well Gas Well 🛛 O	Well 🗵 Other		38	
2. Name of Operator			9. OGRID Number	
Dugan Production Corp.	100	N10	06515	1774 1
3. Address of Operator P. O. Boy 420. Ferminator, NM 8746	00 0420	. N. W.W.	O. Pool name or	
P. O. Box 420, Farmington, NM 87499-0420 Basin Fruitland Coal United Services of Coal Basin Fruitland Coal				
Wen Zoouton	The same of the sa			
Unit Letter F:	1980 feet from the North	line and198	60 feet from	the <u>West</u> line
Section 13 Town	chin 20M Dongo 15W	7 NIM (D)	M. San Ivan Ca	
Section 13 Township 30N Range 15W NMPM San Juan County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
5316' GL				
12. Check App	propriate Box to Indicate Na	ature of Notice, Re	eport or Other	Data
NOTICE OF INTE	_		EQUENT REF	
PERFORM REMEDIAL WORK F	PLUG AND ABANDON 🔲	REMEDIAL WORK		ALTERING CASING 🗌
TEMPORARILY ABANDON ☐ C	CHANGE PLANS	COMMENCE DRILL	ING OPNS □	PLUG AND 🖂
TEM CIVILLE ABANDON	_	OCIVINIZITOE DIVIEL		ABANDONMENT
	MULTIPLE	CASING TEST AND		
	COMPLETION	CEMENT JOB		
OTHER:		OTHER: Compl	etion, tubing	\boxtimes
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
Pressure test casing to 3500#, held. Run cased hole logs. Perforate Fruitland Coal from 490'-496', 502'-507',				
580'-583', 615'-628' w/4 spf (total 104 holes). Acidize w/900 gallons 15% HCL. Frac w/86,560# 20/40 Brady				
sand, 20,720# Super LC sand, 49,972 gallons AmBor Max 1020 gel fluid.				
			•	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE O March 4, 2004				
THE INDICE 4, 2004				
Type or print name John C. Alexande	er E-mail address: johncalexai	nder@duganproductio	n.com Telepho	one No. (505)325-1821
(This space for State use)	/			MAR - 5 2004
ADDROVED DV		W ON B GAS INSPEC	Mar and	
APPPROVED BY				
conditions of approval, it ally.				