In Lieu of Form 3160 (June 1990)	UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT	FI	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY Do not use this form for proposals to di	NOTICE AND REPORTS ON WELLS rill or to deepen or reentry to a different reservoir. Use "APPLICATION OF THE PORTY OF T	5.	Lease Designation and Serial No. SF-078766
ТО І	DRILL" for permit for such proposals	$\begin{array}{c c} A & O & \\ \hline 6. & \\ NM & \\ \end{array}$	If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICATE	7.	If Unit or CA, Agreement Designation Rosa Unit
Type of Well Oil Well X Gas Well	Other	8.	Well Name and No. Rosa Unit #139B
2. Name of Operator WILLIAMS PRODUCTION COMPANY			API Well No. 30-045-31137
3. Address and Telephone No. PO BOX 316 Ignacio, Colorado 81137 (970)563-3308			Field and Pool, or Exploratory Area Blanco Mesa Verde/Basin Dakota
Location of Well (Footage, Sec., T., R., M., or Survey Description) Sur - 1895fsl&1885fwl / BHL - 660fsl&1980fwl, T31N, R6W, sec 17		11.	County or Parish, State San Juan, New Mexico
CHEC	CK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	, REPORT, OR	OTHER DATA
TYPE OF SUBMISSION	Т	YPE OF ACTIO	ON
Notice of Intent Subsequent Report Final Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other <u>see below</u>	-	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)
	ted Operations (Clearly state all pertinent details, and give pertinent da surface locations and measured and true vertical depths for all marker		
	LLC <u>intends</u> to directionally drill this well from the abov attached C-102, operation and directional plan. This we ec 17, T31N, R6W.		
	į.	678910°	117278



HOLD CIGA FOR Pirectional Suvel

14.	I hereby certify that the foregoing is true and correct Signed Larry Higgins	Title <u>Drilling C.O.M</u>	Date	2-27-04
	(This space for Federal or State office use) Approved by Conditions of approval, irany	Title Petr. Eng.	_	Date 3 /4/04

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I PO Box 1980, Hobbs, NM 88241-1980

District II PO Drawer DD, Artesia, NM 88211-0719

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV PO Box 2088, Santa Fe, NM 87504-2088 State of New Mexico Energy, Minerals & Natural Resources Department

Form C–102 ent Revised February 21, 1994 Instructions on back in Submit to Appropriate District Office

OIL CONSERVATION DIVISION VELTON PO Box 2088
Santa Fe, NM 87504-2088
7 PM 2: 00

opriate District Office State Lease – 4 Copies Fee Lease – 3 Copies

AMENDED REPORT


070 Farmington, NM

WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number	'API Number 'Pool Code 'Pool Name		ASIN DAKOTA	
Property Code		erty Name A UNIT	°Well Number 1398	
'OGRID No. 120782	- -	ator Name DUCTION COMPANY	*Elevation 6404	
	10 0 6			

¹⁰ Surface Location Sect ion Township Lot Idn Feet from the North/South line UL or lot no. Range East/West line County Feet from the 17 31N 6W 1895 SOUTH 1885 WEST Κ SAN JUAN ¹¹Bottom Hole Location If Different From Surface UL or lot no Township Lat Idn Feet from the North/South line Feet from the Section Range East/West line County Ν 17 31N 6W 660 SOUTH 1980 WEST SAN JUAN 12 Dedicated Acres ¹³ Joint or Infill ¹⁴ Consolidation Code ⁵Order No. 320.0 Acres - (W/2)

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION





WILLIAMS PRODUCTION COMPANY

Operations Plan

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:

2/19/2004

FIELD:

Basin DK/BlancoMV

WELL NAME:

Rosa #139B

San Juan, NM

SURFACE:

Fed

BH LOCATION:

SESW Sec 17-31N-6W

MINERALS:

Fed

SURF. LOCATION:

NESW Sec 17-31N-6W

ELEVATION:

6,404' GR

LEASE #

SF-078766

MEASURED DEPTH: 8,404'

I. **GEOLOGY:** Surface formation - San Jose

A. FORMATION TOPS: (KB)

Name	TVD	MD	Name	TVD	MD
Ojo Alamo	2,353	2,553	Cliff House	5,373	5,634
Kirtland	2,478	2,691	Menefee	5,423	5,684
Fruitland	3,013	3,261	Point Lookout	5,683	5,944
Picture Cliffs	3,238	3,493	Mancos	5,983	6,244
Lewis	3,528	3,787	Gallup	6,978	7,239
			Greenhorn	7,703	7,964
			Graneros	7,763	8,024
			Dakota	7,893	8,154
			TD	8,143	8,404

- B. MUD LOGGING PROGRAM: None
- C. LOGGING PROGRAM: Cased hole logs
- D. NATURAL GAUGES: Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.

II. DRILLING

- A. MUD PROGRAM: Clear water with benex to 7" casing point. Convert to a LSND mud to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses. Use air w/Air Hammer from 7 in. csg.to TD.
- B. <u>BOP TESTING:</u> While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the rams will be tested to 1500 psi. The surface and intermediate casing strings will be pressure tested to 1500 psi in conjunction with the BOP test before drilling out cement. The drum brakes will be inspected and tested each tour. All tests, inspections and SPR's will be recorded in the tour book as to time and results.

III. MATERIALS

A. CASING PROGRAM:

CASING TYPE	HOLE SIZE	DEPTH (MD)	CASING SIZE	WT. & GRADE
Surface	14-3/4"	+/- 300'	10-3/4"	32.75# H-40
Intermediate	9-7/8"	+/-3974'	7-5/8"	26.4# K-55
Prod. Casing	6-3/4"	+/- 8404'	5-1/2"	17.0# N-80

B. FLOAT EQUIPMENT:

- 1. <u>SURFACE CASING:</u> 9-5/8" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (3) joints of Surface Casing.
- 2. <u>INTERMEDIATE CASING:</u> 7" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install one Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (4) joints to the surface casing. Total centralizers = (26) regular and (3) turbulent.
- 3. <u>PRODUCTION CASING:</u> 4-1/2" whirler type cement nose guide shoe with a latch collar on top of 20" bottom joint. Place marker joint above 5630'. Place one positive standoff turbolizer every other joint. Total turbolizers is 34.

C. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- 1. <u>SURFACE</u>: Slurry: <u>255sx</u> (356 cu.ft.) of "Type III" + 2% CaCl₂ + ¼ # of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). The 100% excess should circulate cement to the surface. WOC 12 hours. Test csg to 1500psi.
- INTERMEDIATE: Lead 625 sx (1302) cu.ft.) of "Type III" 65/35 poz with 8% gel, 1% CaCl₂ and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail 150 sx (209cu.ft.) of "Type III" with 1/4# cello-flake/sk, and 1% CaCl₂ (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.). Use 100% excess in Lead Slurry to circulate to surface. No excess in Tail Slurry. Total volume = 1,511 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.
- 3. PRODUCTION LINER: 10 bbl Gelled Water space. Scavenger: 50sx (130ft³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE, ¼ #/sk cello flake and 4% Phenoseal. (Yield = 2.59 cu.ft./sk, Weight = 11.6 #/gal.). Cement: 215 sx (430° \tag{11} tt³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE, ¼ #/sk cello flake and 4% Phenoseal. (Yield = 2.15 ft³/sk, Weight = 12.3 #/gal.). Displace cement at a minimum of 8 BPM. The 20% excess in lead and tail should cover 100 ft into intermediate casing. Total volume 460ft³. WOC 12 hours

592

IV COMPLETION

A. CBL

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement not circulated to surface..

B. PRESSURE TEST

1. Pressure test 7 5/8" & 5-1/2" casing to 3300# for 15 minutes.

C. STIMULATION

- 1. Stimulate Dakota with approximately 70,000# of 20/40 sand in x-link foam.
- 2. Isolate Dakota with a RBP.
- 3. Stimulate Point Lookout with approximately 80,000# of 20/40 sand in slick water.
- 4. Isolate Point Lookout with a RBP.
- 5. Perforate the Menefee/Cliff House as determined from the open hole logs.
- 6. Stimulate with approximately 80,000# of 20/40 sand in slick water.
- 7. Test each zone before removing bridge plugs.

D. RUNNING TUBING

- 1. <u>Dakota</u>: Run 2-1/16", 3.25#, J-55, IJ tubing with 1/2 mule shoe on bottom, SN with pump-out plug on top of adeem joint and 5 Seal Units. Land tubing approximately 100' below top Dakota perf.
- 2. <u>Mesa Verde:</u> Run 2-1/16", 2.9#, J-55, EUE tubing with a SN (1.91" ID) on top of bottom joint. Land tubing approximately 25' above the bottom Point Lookout perforations.

Carry Hygini Gary Sizemore Sr. Drilling Engineer

