

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry</u>		7. Unit Agreement Name
2. Name of Operator <u>Beard Oil Company C/O W.D. Stricklin</u>		8. Farm or Lease Name <u>FERNANDEZ</u>
3. Address of Operator <u>Box 1543 Farmington, New Mexico 87401</u>		9. Well No. <u>4</u>
4. Location of Well UNIT LETTER <u>E</u> . <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>14 N</u> RANGE <u>7 W</u> NMPM.		10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>6960' Ground</u>		12. County <u>Mckinley</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

It is intended to plug and abandon this well. A plug will be set between 350' to 400' with 10 sacks. Also a 5 sack plug will be placed in the top of the hole and dry hole marker cemented in. It is also intended to cover the pits and clean up the location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. D. Stricklin TITLE Cert. Professional Geol. DATE 7/5/69
APPROVED BY George C. Currey TITLE Sgt. Dist. III DATE 7-7-69
CONDITIONS OF APPROVAL, IF ANY: